



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

OIL CONS. DIV DIST. 3
MAY 10 2017

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test

4-20-17

Operator

Thompson

API#

30-079-23660

Property Name

VUNA #12

(Well Name and Number)

Location: Unit

0

Section

3

Township

13N

Range

9W

Pressure (Shut-in or Producing)

Tubing

170

Intermediate

Casing

176

Bradenhead

0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	0	176					
10 minutes	0	176					
15 minutes	0	176					
20 minutes							
25 minutes							
30 minutes							
5 minute SI	0	176					
						Steady Flow	
						Surges	
						Down to Nothing	
						No Flow	X
						Gas	
						Gas and Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate _____

REMARKS:

By

Alejandro
Lease Operator

(Position)

Witness

NMOCD Test Area:

1