



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3  
MAY 10 2017

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 4-18-17 Operator Thompson API # 20-097-25153  
Property Name Lybbook # RR Location: Unit I Section 12 Township 24N Range 7W  
(Well Name and Number)  
Pressure (Shut-in or Producing) Tubing 190 Intermediate \_\_\_\_\_ Casing 248 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	<u>0</u>		<u>248</u>				
10 minutes	<u>0</u>		<u>248</u>				
15 minutes	<u>0</u>		<u>248</u>				
20 minutes							
25 minutes							
30 minutes							
5 minute SI	<u>0</u>		<u>248</u>				

Steady Flow		
Surges		
Down to Nothing		
No Flow	<u>X</u>	
Gas		<u>✓</u>
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in Bradenhead 0 Intermediate \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Mike Wagner  
Lease Operator  
(Position)

Witness \_\_\_\_\_