

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE,
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
http://www.emnrd.state.nm.us/ocd/

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

			(Subini	t z copies to at	JOVE AUGIE	130)			
Date of Test 4/19/2017		Operator	Merrion O	Merrion Oil Gas Corpora		API#	3003929235		
Property Name Featherstone Federal 2				V) Location: Unit Section 19			Township 26N Range 02W		
		(Well Name	and Number)						
Pressure (She	ut-in or Prod	lucing)	Tubing _	OO Interme	diate	Casing _	15 Br	adenhead	
OPEN	BRADENHI	EAD AND	INTERMEDIA	TE TO ATMOS	PHERE INC	DIVIDUALLY FO	R 15 MINU	TES EACH	
[Bradenhead			Intermediate		1			
Time	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Braden Flow	head Intermediate	
5 minutes	0	115				Steady Fig	ow		
10 minutes	0	115				Surg	es		
15 minutes	0	115				Down to Nothin			
20 minutes	0	115				No Fid			
25 minutes	0	115				Gas and Wat	as		
30 minutes	0	115				Wat			
5 minute SI]			
If bradenh	ead flowed v	vater, che	eck all of the d	escriptions tha	t apply bel	low:			
Clear Fresh Salty Sulfur Black									
5 Minute S	hut-in R	radenhea	d ()	Intermediate					
5 Millate 5	nucii D	raceinea		memodiate		OIL CON	15 pm		
REMARKS:						MAY	O. DIV DIS	ST. 3	
						· · · · · · · · · · · · · · · · · · ·	O 4 ZUIV		
								(1)	
								, 100	
By Kyle Davis Witness Lease of erator									
	Lease	ofer	ator					10	
		(Positio							