



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONS. DIV DIST. 3

MAY 30 2017

OIL CONSERVATION DIVISION

AZTEC DISTRICT OFFICE

1000 RIO BRAZOS ROAD

AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-30-17 Operator Logos OPLLC API #30-0 39-07117
Property Name Sicardita 89 Tubal Well No. 4 Location: Unit M Section 11 Township 27 Range 3
Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 92 Intermediate 114 Casing 112 Bradenhead 103

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>4</u>		<u>109</u>		
10 min	<u>1</u>		<u>111</u>		
15 min	<u>1</u>		<u>113</u>		
20 min	<u>0</u>		<u>115</u>		
25 min	<u>0</u>		<u>116</u>		
30 min	<u>0</u>		<u>117</u>		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>/</u>	
Surges		
Down to Nothing		
Nothing		
Gas	<u>/</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 18

INTERMEDIATE 114

REMARKS:

mid/light blow when opened. started flowing/producing
when annulled. light blow at 5 min. 10. 15. 20 light at 25-30
Sys analysis sent e-mail

By Eugene Burbank

Witness Monica Kunkling

Lead
(Position)

E-mail address _____