



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 5-16-17 Operator: Enervest Operating, LLC API # 30-039-21522

Property Name: Champlin Well No. 2A Location: Unit: N Section: 35 Township: 27N Range: 4W

Well Status(Shut-In or Producing) Initial PSI: Tubing 60 Intermediate      Casing 60 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>60</u>		
10 min	<u>0</u>		<u>60</u>		
15 min	<u>0</u>		<u>60</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<input checked="" type="checkbox"/>
Nothing	
Gas	
Gas & Water	
Water	

OIL CONS. DIV DIST. 3

JUN 09 2017

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR      FRESH      SALTY      SULFUR      BLACK     

5 MINUTE SHUT-IN PRESSURE BRADENHEAD      INTERMEDIATE     

REMARKS:

By Alcasio Chacon

Witness     

Operator

(Position)

E-mail address