



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6176 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-JUNE-2017 Operator COROLO API #30-0 45-21821

Property Name SCOTT Well No. 10 Location: Unit M Section 4 Township 31 Range 10

Well Status(Shut-In or Producing) Initial PSI: Tubing N/A Intermediate N/A Casing 80 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME		Int			
5 min	0	N/A	80		
10 min	0		80		
15 min	0		80		
20 min				N/A	
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	X	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND NOTHING CAME OUT

WELL IS SLIM HOLE

By Kalend

Witness

John B. B...

OIL CONS. DIV DIST. 3

(Position)

JUN 08 2017

E-mail address _____