

NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test /- JUNE - LOT / Operator CONDO API #30-0 45 - 22 / 20
Property Name LUENG A Well No. 7 Location: Unit Section Township 31 Range 10
Well Status(Shut-In or Producing) Initial PSI: Tubing MA Intermediate MA Casing Bradenhead O
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH
PRESSURE FLOW CHARACTERISTICS Testing Bradenhead INTERM BRADENHEAD INTERMEDIATE
TIME O N/A 80 Steady Flow Surges
15 min Down to Nothing
20 min Nothing
25 min Gas
30 min Gas & Water
Water
If bradenhead flowed water, check all of the descriptions that apply below:
CLEAR FRESH SALTY SULFUR BLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE N/A
REMARKS: OFFIED THE BRADENHEAD AND NOTHING CAME OUT.
By Lylen Witness MMBWM
OIL CONS. DIV DIST. 3
(Position) JUN 0 8 2017
E-mail address