



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3distric.htm](http://emnrd.state.nm.us/ocd/District%20III3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-JUNE-2017 Operator BURLINGTON API #30-0 45-25114
Property Name CULPEPPER MARTIN Well No. 1E Location: Unit P Section 31 Township 32 Range 12
Well Status (Shut-In or Producing) Initial PSI: Tubing 69 Intermediate N/A Casing 73 Bradenhead 110

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	BH	Bradenhead Int	Csg	INTERM Int	Csg	
TIME						
5 min	<u>1</u>	<u>N/A</u>	<u>74</u>			
10 min	<u>.6</u>	<u></u>	<u>74</u>			
15 min	<u>.4</u>	<u></u>	<u>74</u>			
20 min	<u>.4</u>	<u></u>	<u>74</u>			
25 min	<u>.3</u>	<u></u>	<u>74</u>			
30 min	<u>.3</u>	<u></u>	<u>75</u>			

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>X</u>	
Surges		
Down to Nothing		
Nothing		
Gas	<u>X</u>	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 10.8

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND IT BLEW DOWN TO
3 PSI AND FLOWED FOR THE ENTIRE TEST.
REQUESTED A GAS ANALYSIS

By Tim Ferguson
ALSO Tim
(Position)

Witness John Dufan

OIL CONS. DIV DIST. 3

E-mail address _____

JUN 09 2017