



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test

5-9-17

Operator

THOMPSON

API#

30-039-24133

30-039-24133

Property Name

State #6

Location: Unit

1

Section

2

Township

23N

Range

7W

(Well Name and Number)

Pressure (Shut-in or Producing)

Tubing

2 1/2

Intermediate

Casing

2 1/2

Bradenhead

0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead		
	BH Blowdown	Casing Monitor	Intermediate Monitor
5 minutes	0	2 1/2	
10 minutes	0	2 1/2	
15 minutes	0	2 1/2	
20 minutes			
25 minutes			
30 minutes			
5 minute SI	0	2 1/2	

Intermediate	
Intermediate Blowdown	Casing Monitor

	Bradenhead Flowed	Intermediate Flowed
Steady Flow		
Surges		
Down to Nothing		
No Flow	X	
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in

Bradenhead

0

Intermediate

OIL CONS. DIV DIST. 3

JUN 05 2017

REMARKS:

By

Mike Wagoner  
Lease Operator  
(Position)

Witness

NMOCD Test Area:

1