



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-10-17 Operator THOMPSON API # 30-039-24219  
Property Name Dunn #13 Location: Unit A Section 4 Township 23N Range 7W  
(Well Name and Number)  
Pressure (Shut-in or Producing) Tubing 160 Intermediate \_\_\_\_\_ Casing 280 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	<u>0</u>	<u>280</u>					
10 minutes	<u>0</u>	<u>280</u>					
15 minutes	<u>0</u>	<u>280</u>					
20 minutes							
25 minutes							
30 minutes							
5 minute SI	<u>0</u>	<u>280</u>					
						Steady Flow	
						Surges	
						Down to Nothing	
						No Flow	<u>X</u>
						Gas	<u>✓</u>
						Gas and Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in Bradenhead 0 Intermediate \_\_\_\_\_

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Mike Wagoner  
Lease Operator  
(Position)

Witness \_\_\_\_\_