



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test

3-9-17

Operator

THOMPSON

API #

30-139-25236

Property Name

Spurte #8

(Well Name and Number)

Location: Unit

A

Section

2

Township

23N

Range

2W

Pressure (Shut-in or Producing)

Tubing

84

Intermediate

Casing

169

Bradenhead

0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	169					
10 minutes	0	169					
15 minutes	0	169					
20 minutes							
25 minutes							
30 minutes							
5 minute SI	0	169					

Steady Flow		
Surges		
Down to Nothing		
No Flow	X	
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_ OIL CONS. DIV DIST. 3

5 Minute Shut-in Bradenhead 0 Intermediate \_\_\_\_\_

JUN 05 2017

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By \_\_\_\_\_

Mike Wagoner  
Lease Operator  
(Position)

Witness \_\_\_\_\_