



NEW MEXICO ENERGY, MINERALS
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 5-10-17 Operator Thompson API # 30-039-25507
Property Name Dunn #19 Location: Unit A Section 4 Township 23N Range 7W
(Well Name and Number)
Pressure (Shut-in or Producing) Tubing 119 Intermediate _____ Casing 129 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>129</u>				Steady Flow	
10 minutes	<u>0</u>	<u>129</u>				Surges	
15 minutes	<u>0</u>	<u>129</u>				Down to Nothing	
20 minutes						No Flow	<u>X</u>
25 minutes						Gas	<u>✓</u>
30 minutes						Gas and Water	
5 minute SI	<u>0</u>	<u>129</u>				Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0 Intermediate _____

REMARKS:

By Mike Wagoner
Lease Operator
(Position)

Witness _____

NMOCD Test Area: