Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018 5. Lease Serial No. NMNM101058

SUNDRY NOTICES AND REPORTS ON WELLS	
Do not use this form for proposals to drill or to re-enter an	
shandanad wall lies fame 2460 2 (ADD) famoush anamasala	

abandoned well. Use form 3160-3 (APD) for such proposals.					6. If Indian, Allottee or Tribe Name EASTERN NAVAJO			
SUBMIT IN TRIPLICATE - Other instructions on page 2					7. If Unit or CA/Agreement, Name and/or No. NMNM133481X			
1. Type of Well	8. Well Name and No. PINON UNIT 306H							
	9. API Well No.							
JUNIPER RESRC EXPLRN C	30-045-35638-00-X1							
3a. Address 3624 OAK LAWN AVE STE 222 DALLAS, TX 75219 3b. Phone No. (include area code) Ph: 214-443-0001 OIL CONS DIV DIST					Field and Pool or Exploratory Area PINON UNIT HZ			
4. Location of Well (Footage, Sec., T.	11. County or Parish, State							
Sec 16 T24N R10W SWSW 1	9 2017	SAN JUAN COUNTY, NM						
12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA								
TYPE OF SUBMISSION	TYPE OF ACTION							
☐ Notice of Intent	☐ Acidize	□ Deep	epen Pr		ion (Start/Resume)	☐ Water Shut-Off		
_	☐ Alter Casing	☐ Hyd	raulic Fracturing	☐ Reclamation		☐ Well Integrity		
Subsequent Report	☐ Casing Repair	□ New	Construction	☐ Recomp	olete	☑ Other		
☐ Final Abandonment Notice	☐ Change Plans		and Abandon		arily Abandon			
BP	☐ Convert to Injection	Plug		□ Water I				
13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplete horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Note: Mo-Te preset surface casing @ 324' 6/1/17: MIRU Aztec 920 drilling rig. NU BOP's. RU BOP testers. Test BOP's, pipe rams, blind rams, choke manifold, all valves, HCR, TIW valve, upper kelly cock, check valve - 250 psig low 5 min, 3000 psig high 10 mins. Tested annular preventer 250 psig low 5 min, 2100 psig high 10 mins. Changed out check valve and re-test check valve, TIW, upper kelly cock - 250 psi low 5 mins, 3000 psig high 10 mins. TEST GOOD (Witnessed by BLM - Ray) Tested 9 5/8" surface casing to 1500 psig for 30 mins. TEST GOOD. 6/2 - 6/4/17: Drilled 8 3/4" intermediate section and curve to TD of 5,200' MD (4,799' TVD).								
14. I hereby certify that the foregoing is true and correct. Electronic Submission #378218 verified by the BLM Well Information System For JUNIPER RESRC EXPLRN CO LLC, sent to the Farmington Committed to AFMSS for processing by JACK SAVAGE on 06/16/2017 (17JWS0159SE)								
Name (Printed/Typed) JUSTIN DAVIS Title VP OPERATIONS								
Signature (Electronic S	Signature (Electronic Submission) Date 06/07/2017					,		
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved By ACCEPTED			JACK SAVAGE TitlePETROLEUM ENGINEER Date 06/			Date 06/16/2017		
Conditions of approval, if any, are attached certify that the applicant holds legal or equivalent would entitle the applicant to conductive to the conductive to the applicant to conductive the appli	Office Farmington							
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s				willfully to ma	ake to any department or ag	gency of the United		

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **

Additional data for EC transaction #378218 that would not fit on the form

32. Additional remarks, continued

6/4/2017: TOH f/ casing. Run 7", 23 ppf, J-55 LTC casing to 5,132". 128 jts total. RU Halliburton cementers. M&P 10 bbls mud flush, 20 bbls chemical wash, 10 bbls FW, 375 sx Lead (131.6 bbls) HalCem cement @ 12.3 ppg, 1.97 yield and Tail 350 sx VariCem @ 13.5 ppg, 1.3 yield. Displaced with mud and bumped plug. Floats held. 40 bbls good cement to surface. WOC.

Tested 7" intermediate casing to 1500 psig for 30 mins. TEST GOOD.

No a service