



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

30-039-05332

Date of Test 6-27-17 Operator THOMPSON API # 30-039-05332  
Property Name Lybrook #17 Location: Unit A Section 27 Township 24 Range 7W  
(Well Name and Number)  
Pressure (Shut-in or Producing) 0 Tubing 255 Intermediate 0 Casing 256 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	0	256	0				
10 minutes	0	256	0				
15 minutes	0	256	0				
20 minutes				0	256	X	X
25 minutes				0	256		
30 minutes				0	256		
5 minute SI	0	256	0	0	256		

Steady Flow		
Surges		
Down to Nothing		
No Flow	X	X
Gas		
Gas and Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in Bradenhead 0 Intermediate 0

OIL CONS. DIV DIST. 3

JUL 03 2017

REMARKS:

\_\_\_\_\_  
\_\_\_\_\_  
\_\_\_\_\_

By Mike Wagner  
Lease Operator  
(Position)

Witness John D. Brown