



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

JUL 06 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-6-2017 Operator ConocoPhillips API #30-0 39-07422

Property Name San Juan 28-7 Unit Well No. 22 Location: Unit H Section 17 Township 28 Range 7

Well Status (~~Shut In~~ or Producing) Initial PSI: Tubing 83 Intermediate 0 Casing 88 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
TIME		Int	Csg	Int	Csg
5 min	0	0	89	0	90
10 min	0	0	89	0	91
15 min	0	0	90	0	91
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	X
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Opsi

INTERMEDIATE Opsi

REMARKS:

Light puff to nothing on BH when opened. Very light puff on BH when opened
Nothing on intermediate when opened, nothing after five minute shut in.

By _____

Witness J. H. H. NMCD

[Signature]
(Position)

E-mail address _____