



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

**BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 5-31-17 Operator: Enervest Operating, LLC API # 30-039-29567

Property Name: Champlin Well No. 5B Location: Unit: E Section: 25 Township: 27N Range: 4W

Well Status(Shut-In or Producing) Initial PSI: Tubing 130 Intermediate      Casing 130 Bradenhead 80

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		130		
10 min	0		120		
15 min	0		115		
20 min	0		115		
25 min	0		110		
30 min	0		110		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <input checked="" type="checkbox"/>	
Surges <input type="checkbox"/>	
Down to Nothing <input type="checkbox"/>	
Nothing <input type="checkbox"/>	
Gas <input type="checkbox"/>	
Gas & Water <input type="checkbox"/>	
Water <input type="checkbox"/>	

OIL CONS. DIV DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

JUN 09 2017

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE     

REMARKS:

Blows Down to 0 in about 1min

By Alcasio Chacon

Witness     

Operator

(Position)

E-mail address