

## OIL CONS. DIV DIST. 3

JUN 26 2017

NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENTOIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://emnrd.state.nm.us/ocd/DistrictIII/3district.htm>

## BRADENHEAD TEST REPORT

(Submit 1 copies to above address)

Date of Test May 11, 2017 Operator DJ Simmons API #30-0 45-22802

Property Name Simmons E Well No. 2A Location: Unit E Section 23 Township 29N Range 09W

Pressure (Shut-In or Producing) Producing Tubing 9 Intermediate 3 Casing 38 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

## PRESSURES:

TESTING TIME	BRADENHEAD			INTERMEDIATE	
	BH	INT	CSG	INT	CSG
5 minutes	0	3	38	0	38
10 minutes	0	3	38	0	38
15 minutes	0	3	38	0	38
20 minutes					
25 minutes					
30 minutes					

Steady Flow

Surges

Down to Nothing

Nothing

Gas

Gas &amp; Water

Water

BRADENHEAD INTERMEDIATE

FLOWED

FLOWED

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN \_\_\_\_\_ BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

BH and Intermediate blew down to nothing

Tested H2S on both BH and Intermediate showed 0ppm

By Tylynn Birdsley Witness \_\_\_\_\_

Lease Operator

(Position)