



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-23-17 Operator CHRISTOPHER M. MONROE API #30-015-27706

Property Name YALBERT Well No. B620 Location: Unit B Section 20 Township 32 Range 6

Well Status(Shut-In or Producing) Initial PSI: Tubing 9 Intermediate Casing 9 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>9</u>		
10 min	<u>0</u>		<u>9</u>		
15 min	<u>0</u>		<u>9</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>0</u>
Gas	
Gas & Water	
Water	

OIL CONS. DIV DIST.
JUN 29 2017

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

NO FLOW AFTER 5 MIN TEST STILL 0

By [Signature]
HDI
(Position)

Witness

E-mail address