

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

Form C-103
May 27, 2004

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

WELL API NO.
30-045-11403

5. Indicate Type of Lease
STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

7. Lease Name or Unit Agreement Name
Decker LS

8. Well Number
1

9. OGRID Number
000778

10. Pool name or Wildcat
Blanco Mesaverde

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐

2. Name of Operator

BP America Production Company - Attn: Mary Corley

3. Address of Operator

P.O. Box 3092 Houston, TX 77253

4. Well Location

Unit Letter **M** : **1014** feet from the **South** line and **959** feet from the **West** line
Section **17** Township **32N** Range **10W** NMPM **San Juan** County

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

6142' GR

Pit or Below-grade Tank Application ☐ or Closure ☐

Pit type _____ Depth to Groundwater _____ Distance from nearest fresh water well _____ Distance from nearest surface water _____

Pit Liner Thickness: _____ mil Below-Grade Tank: Volume _____ bbls; Construction Material _____

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐

OTHER: _____

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ P AND A ☒
CASING/CEMENT JOB ☐

OTHER: _____

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

01/13/2006 MIRUSU Blow down well. NDWH. NU BOP. TOH w/2 3/8" TBG. TIH w /CMT retainer & set @ 4664'. Pumped CMT below & on top of retainer - up to 4200'. TOH. RU, TIH & tag @ 3870'. Load hole & attempt to test - unsuccessful. TOH. TIH & set fullbore @ 2860' & test down TBG. Test OK. Notified NMOCD for approval - Ok. TIH w/BP & test CSG. Leak @ TOL. Attempt to test 7; CSG - unsuccessful. TOH. RU & log well from 3870' to surface. Met w/ Steve Hayden & Henry Villanueva - no SQZ holes needed. RU & pumped CMT plug from 2900' to 2700'. TIH & tag CMT @ 2530'. RU & test CSG - Ok. RU & pump CMT plugs from 2530' to 2303'; from 1550' to 1298'; & from 400' to surface. Cut off wellhead. Install P&A marker.

01/17/2006 RDMOSU Turn location over to environmental group for surface restoration..

I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines ☐, a general permit ☐ or an (attached) alternative OCD-approved plan ☐.

SIGNATURE Mary Corley TITLE Sr. Regulatory Analyst DATE 01/18/2006
Type or print name Mary Corley E-mail address: corleym@bp.com Telephone No. 281-366-4491

For State Use Only

APPROVED BY: H. Villanueva TITLE DEPUTY OIL & GAS INSPECTOR, DIST. 4 DATE APR 06 2006
Conditions of Approval (if any): 4-6-06