



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III3distric.htm>

01

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-7-17 Operator Encana Oil & Gas API #30-0 43-21118

Property Name North Flamingo Unit Well No. 242H Location: Unit H Section 26 Township 23N Range 7W

Well Status (Shut-In or Producing) Initial PSI: Tubing 56 Intermediate N/A Casing 107 Bradenhead 3.5

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>2</u>	<u>N/A</u>	<u>108</u>	<u>N/A</u>	<u>N/A</u>
10 min	<u>2</u>	<u>N/A</u>	<u>116</u>	<u>N/A</u>	<u>N/A</u>
15 min	<u>2</u>	<u>N/A</u>	<u>115</u>	<u>N/A</u>	<u>N/A</u>
20 min	<u>2</u>	<u>1</u>	<u>110</u>	<u>N/A</u>	<u>N/A</u>
25 min	<u>2</u>	<u>1</u>	<u>111</u>	<u>N/A</u>	<u>N/A</u>
30 min	<u>2</u>	<u>N/A</u>	<u>114</u>	<u>N/A</u>	<u>N/A</u>

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>X</u>
Nothing	<u>N/A</u>
Gas	<u>N/A</u>
Gas & Water	<u>N/A</u>
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 2

INTERMEDIATE N/A

REMARKS:

Previous Name Lybrook H26-01H - Running Plugger
Lost BH shut

By

Witness

Arthur Sullivan
Lead Tech

(Position)

OIL CONS. DIV DIST. 3

E-mail address arthur.sullivan@encana.com

JUL 10 2017