



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 2-6-17 Operator Encana O&G API #30-0 43-21126
Property Name Lybrook Well No. H-32 Location: Unit H Section 32 Township 23N Range 6W
Well Status (Shut-In or Producing) Initial PSI: Tubing 33 Intermediate N/A Casing 116 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead		INTERM			BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	0		116			9:12	Steady Flow
10 min	0		116			9:17	Surges
15 min	0		116			9:22	Down to Nothing
20 min	0		116			9:27	Nothing
25 min	0		116			9:32	Gas
30 min	0		116			9:37	Gas & Water
							Water

	X	N/A

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Plunger Running - Flowing - Left BH shut. 55

By Arthur Sullivan
Lead Tech
(Position)

Witness _____

OIL CONS. DIV DIST. 3

JUL 10 2017

E-mail address arthur.sullivan@encana.com