



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170

http://emnr.state.nm.us/ocd/District III/3distric.htm

02

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 2-7-12 Operator Encana Oil & Gas API #30-0 43-21133

Property Name North Alamo Unit Well No. 243 H Location: Unit H Section 26 Township 23 N Range 2 W

Well Status (Shut-In or Producing) Initial PSI: Tubing 121 Intermediate N/A Casing 214 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
5 min	<u>0</u>	<u>N/A</u>	<u>214</u>		
10 min	<u>0</u>		<u>214</u>	<u>N</u>	
15 min	<u>0</u>		<u>214</u>		
20 min	<u>0</u>		<u>213</u>		
25 min	<u>0</u>		<u>213</u>		
30 min	<u>0</u>	<u>N/A</u>	<u>214</u>		

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing

Nothing X

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Plunger Running - Previous Name Lybrook H26-02H
Left BH shut

By Arthur Sullivan

Witness _____

Lead Tech
(Position)

OIL CONS. DIV DIST. 3

E-mail address arthur.sullivan@encana.com

JUL 10 2017