Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

JUL 0 3 2017

RECEIVED ELECTRONIC REPORT

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

| SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-entermanu OF LAND MANAG abandoned well. Use form 3160-3 (APD) for such proposals. | | | | | 5. Lease Serial No. 751081035 6/17 Indian, Allottee or Tribe Name UTE MOUNTAIN UTE | |
|--|--|---|---|--|---|------------------|
| SUBMIT IN TRIPLICATE - Other instructions on page 2 | | | | | 7. If Unit or CA/Agreement, Name and/or No. | |
| Type of Well Gas Well | | | 8. Well Name and No. HSGU 193 | | | |
| Name of Operator BIYA OPERATORS INC | JUBAL TERRY ersifiedresourcesinc.com | | | 9. API Well No. 30-045-10209-00-S1 | | |
| 3a. Address 1789 W. LITTLETON BLVD. LITTLETON, CO 80120 | | 3b. Phone No. (include area code) Ph: 303-797-5417 Fx: 303-797-5418 | | | 10. Field and Pool or Exploratory Area HORSESHOE GALLUP | |
| 4. Location of Well (Footage, Sec., T. |) | | | 11. County or Parish, State | | |
| Sec 34 T31N R16W SWNE 19 | | | SAN JUAN COUNTY, NM | | | |
| 12. CHECK THE AP | PROPRIATE BOX(ES) | TO INDICA | TE NATURE OF | NOTICE, | REPORT, OR OTH | ER DATA |
| TYPE OF SUBMISSION | TYPE OF ACTION | | | | | |
| Notice of Intent | ☐ Acidize | ☐ Dee | epen | □ Product | ion (Start/Resume) | ☐ Water Shut-Off |
| ☐ Subsequent Report | ☐ Alter Casing | | draulic Fracturing | ☐ Reclama | ation | ■ Well Integrity |
| | ☐ Casing Repair | _ | w Construction | ☐ Recomp | | Other |
| ☐ Final Abandonment Notice | ☐ Change Plans ☐ Convert to Injection | | g and Abandon | | arily Abandon | |
| | | Plug Back | | | | |
| If the proposal is to deepen directiona Attach the Bond under which the wor following completion of the involved testing has been completed. Final Ab determined that the site is ready for fi BIYA Operators Inc. will be test request. The well will be tested | e locations and measur in file with BLM/BIA ele completion or recor requirements, includi | red and true ve Required sub mpletion in a r ng reclamation BLM's | rtical depths of all pertinosequent reports must be new interval, a Form 3160, have been completed a OIL CO | ent markers and zones. filed within 30 days 0-4 must be filed once | | |
| 14. I hereby certify that the foregoing is | true and correct | | ī | | | |
| Fire Edy Certify that the folegoing is the and confect. Electronic Submission #380471 verified by the BLM Well Information System For BIYA OPERATORS INC, sent to the Durango | | | | | | |
| Name (Printed/Typed) JUBAL TE | LEY HITCHELL on Title AGENT | 07/05/2017 (| (17ACH0043SE) | | | |
| Signature (Electronic S | Date 07/03/20 | 17 | | | | |
| | THIS SPACE FO | R FEDERA | AL OR STATE (| OFFICE US | SE | |
| Approved By Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon. | | | Title V | MSZ | | 7 (c/2017 |

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)
** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** MOCDA Accepted For Record

Proposed Procedure for testing Horseshoe Gallup UMUT Wells.

- Move onto location with a pumpjack and all other necessary equipment to pump and test well.
- 2) Pump well until stabilized production is achieved and flush production has been pumped out.
- 3) To start the test, a BLM Technician will have to verify the level of oil in the tank or to verify the tank is empty.
- 4) The tank will be properly sealed and witnessed by a BLM Technician.
- 5) Test all lines from well head to test tank.
- 6) Pump well daily and record production
- 7) The test will last 14 days exactly.

1

- 8) At the end of the 14 days the test will conclude.
- 9) BLM Technician will verify the level of oil in the test tank.
- 10) Once BLM has given the ok on this test, remove seal, load oil onto vac truck and move oil to main TB.
- 11) At the conclusion of the gaging, the oil will be removed from the tank using a Vacuum truck.
- 12) Nipple down flow lines and move test tank to next location. Reclaim temporary berm.

BIYA Operators, Inc.

Tribal Lease: 751-08-1035 Well: Horseshoe Gallup #193

Location: 1980' FNL & 1980' FEL

Sec. 34, T. 31 N., R. 16 W. San Juan County, New Mexico

Discussion of Well Testing: The intent of this testing is to determine whether this well can produce on an economic basis as per 43CFR, 3162.3-4(a). According to BLM records this well has not produced at all since 2001. This test will allow the Operator to demonstrate economic production over a period of 14 **consecutive** days. Any mechanical failure, weather, or anything else that will cause the well not to produce during this 14 day test period is the responsibility of the Operator. The BLM will measure the amount of oil produced during this 14 day test and then determine if this well is an economic producer or not. If this well fails to meet the economic threshold, then the well must be plugged. The following Conditions of Approval will give specific rules. Testing must take place **immediately** as your 60 day requirement to produce, plug, or demonstrate economic production is July 14, 2017. If you fail to start the testing by this date, then this well will be ruled non-economic and immediate plugging must take place.

Notice: This requirement applies to all 13 of the wells that the BLM has issued the 60 day letters to. If this testing program does not start within the 60 day period ending July 14, 2017, then **all** 13 wells will be determined uneconomic and immediate plugging must take place. This is not negotiable.

Conditions of Approval – Well Testing:

- 1. Notify this office at least 72 hours prior to commencing testing operations.
- 2. The test will be run for a period of 14 consecutive days. No exceptions. Whatever oil volume is in the tank after 14 days will be used as the basis for determining if the well is capable of production in paying quantities. Report produced water volumes also.
- 3. The Operator is fully responsible for the testing. Any failure that occurs during the 14 day test cannot be used to ask for relief.
- 4. If the well does not produce in paying quantities, the BLM will issue a letter to the operator that the well did not pass the test. In this letter we will give the Operator 30 days to submit a Sundry Notice, Notice of Intent to plug the well. You will have 90 days after the approval of the Sundry Notice to complete the plugging of the well. Appeal right will be given in this letter.