



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-11-17 Operator: Enervest Operating, LLC API # 30-039-82260

Property Name: Jicarilla B Well No. 04 Location: Unit: H Section: 21 Township: 26N Range: 5W

Well Status(Shut-In or Producing) Initial PSI: Tubing 90 Intermediate Casing 90 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>Ø</u>		<u>97</u>		
10 min	<u>Ø</u>		<u>97</u>		
15 min					
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>✓</u>
Nothing	
Gas	
Gas & Water	
Water	

OIL CONS. DIV DIST. 3
MAY 24 2017

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS: Well blew dead after 2 seconds

By Robert Gentry
Operator
(Position)

Witness

E-mail address