



NEW MEXICO ENERGY, MINERALS  
AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-29-17 Operator THOMPSON API # 30-039-23406  
Property Name Escondido Gas Unit 24 Location: Unit H Section 19 Township 24 Range 7W  
(Well Name and Number)  
Pressure (Shut-in or Producing) \_\_\_\_\_ Tubing 2 Intermediate \_\_\_\_\_ Casing 183 Bradenhead 64

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Flowed	Intermediate Flowed
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		
5 minutes	<u>0</u>	<u>183</u>					
10 minutes	<u>0</u>	<u>183</u>					
15 minutes	<u>0</u>	<u>183</u>					
20 minutes	<u>0</u>	<u>183</u>					
25 minutes	<u>0</u>	<u>183</u>					
30 minutes	<u>0</u>	<u>183</u>					
5 minute SI	<u>0</u>	<u>183</u>					
						Steady Flow	
						Surges	
						Down to Nothing	<u>X</u>
						No Flow	
						Gas	
						Gas and Water	
						Water	

OIL CONS. DIV DIST 3

JUL 03 2017

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in Bradenhead 40 Intermediate \_\_\_\_\_

REMARKS:

By Mike Dugan  
Team Operator  
(Position)

Witness John Dugan

