



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emmr.state.nm.us/ocd/District/3/district.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 25 JULY-2017 Operator XJO API #30-0 45 23048

Property Name BEALON LAKE COM Well No. 2A Location: Unit C Section 36 Township 31 Range 11

Well Status (Shut-In or Producing) Initial PSI: Tubing 385 Intermediate 114 Casing 110 Bradenhead 385

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	10	N/A	110		
10 min	7		110		
15 min	5		110		
20 min	4		110		
25 min	4		110		
30 min	3		110		

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow	
Surges	
Down to Nothing	
Nothing	
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 210

INTERMEDIATE N/A

REMARKS:

OPENED THE BRADENHEAD AND BLEW DOWN TO
3851 AND FLOWED FOR THE ENTIRE TEST

By

LINE Q.
(Position)

Witness

[Signature]

E-mail address _____

OIL CONS. DIV DIST. 3
JUL 28 2017