

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company WPX Energy Production, LLC		Contact Deborah Watson	
Address PO Box 640		Telephone No. 505-333-1880	
Facility Name Chaco 2308 09A #145H		Facility Type Well Site	
Surface Owner Federal	Mineral Owner Federal	API No. 30-045-35496	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	9	23N	08W	1,180	North	1,750	East	San Juan

Latitude N36.245745 Longitude W107.683798

NATURE OF RELEASE

Type of Release crude oil and produced water	Volume of Release est 10 bbl	Volume Recovered 6 bbl
Source of Release corrosion hole in divert line	Date and Hour of Occurrence 5/27/17 11:25	Date and Hour of Discovery 5/27/17 11:25
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required Notice given within 24 hours of release.	If YES, To Whom? Cory Smith (NMOCD) Vanessa Fields (NMOCD) Whitney Thomas (BLM-FFO)	
By Whom? N/A	Date and Hour 6/1/17 email at 9:50 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

OIL CONS. DIV DIST. 3

JUN 13 2017


If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
A corrosion hole was located in an underground line. A spec truck was called to the location and fluids were recovered. The location was shut-in.

Describe Area Affected and Cleanup Action Taken.*

- A spec truck recovered approximately 6 bbl of released fluids.
- The fluids remained on location.
- Cleanup is currently underway. Due to the location of the release, equipment has been temporarily removed from the facility. Impacted soil is being removed from the location and transported to landfarm for disposal.
- WPX will notify BLM and OCD prior to confirmation sampling. Samples will be collected and laboratory analyzed for BTEX, TPH (GRO/DRO/MRO), and chlorides.
- Additional cleanup actions will be taken if analytical laboratory results exceed NMOCD recommended remedial action levels based on site ranking.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 		OIL CONSERVATION DIVISION	
Printed Name: Deborah Watson		Approved by Environmental Specialist: 	
Title: Environmental Specialist		Approval Date:	Expiration Date:
E-mail Address: deborah.watson@wpxenergy.com	Conditions of Approval: <i>Within 60 Day's</i>		Attached <input type="checkbox"/> <i>N/A</i>
Date: 06/12/2017	Phone: 505-333-1880		

* Attach Additional Sheets If Necessary #NUF 1715239278

①