

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company WPX Energy Production	Contact Deborah Watson
Address PO Box 640, Aztec NM	Telephone No. 505-333-1880
Facility Name MC 5 Com #112H	Facility Type Well Pad

Surface Owner Federal	Mineral Owner Federal (NMNM-119786)	API No. 30-045-35605
-----------------------	-------------------------------------	----------------------

LOCATION OF RELEASE

Unit Letter D	Section 33	Township 24N	Range 8W	Feet from the 1276	North/South Line North	Feet from the 405	East/West Line West	County San Juan
------------------	---------------	-----------------	-------------	-----------------------	---------------------------	----------------------	------------------------	--------------------

Latitude N36.27485 Longitude W107.69406 NAD83

NATURE OF RELEASE

Type of Release Fire/ Minor Liquids	Volume of Release <1.0 bbl	Volume Recovered 0 bbl
Source of Release Compressor	Date and Hour of Occurrence 6/20/17	Date and Hour of Discovery 6/20/17 19:45
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Vanessa Fields, NMOCD @ 20:06 Whitney Thomas, BLM-FFO @ 20:12 BLM 24-HR Emergency Hotline @ 20:28	
By Whom? Christopher Foeller	Date and Hour 6/20/17 (see above) follow up emails sent	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

OIL CONS. DIV DIST. 3

Describe Cause of Problem and Remedial Action Taken.*



JUL 03 2017

Fire at compressor. Location was shut-in. San Juan County Fire Department was dispatched to the location. Fire was extinguished by San Juan County Fire Department at approximately 21:00 on 6/20.

Describe Area Affected and Cleanup Action Taken.*

- No injuries.
- Fire and damages contained to the compressor and compressor skid.
- Minor impact to soils below and around the compressor. No fluids migrated off location. Cleanup of impacted soils completed on 6/23.
- Impacted compressor removed from location.
- No further action required.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Deborah Watson	Approved by Environmental Specialist: 	
Title: Environmental Specialist	Approval Date: 7/12/17	Expiration Date:
E-mail Address: deborah.watson@wpxenergy.com	Conditions of Approval: —	Attached <input type="checkbox"/>
Date: 7/3/17	Phone: 505-333-1880	

* Attach Additional Sheets If Necessary #NOF 171725 2126