

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office to  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company <b>ConocoPhillips Company</b>	Contact <b>Lisa Hunter</b>
Address <b>3401 East 30<sup>th</sup> St, Farmington, NM</b>	Telephone No. <b>(505) 258-1607</b>
Facility Name: <b>Bolin Hardie #1</b>	Facility Type: <b>Gas Well</b>

Surface Owner <b>Federal – BLM</b>	Mineral Owner <b>Federal – SF-078049-A</b>	API No. <b>300-45-20126</b>
------------------------------------	--	-----------------------------

**LOCATION OF RELEASE**

Unit Letter <b>D</b>	Section <b>34</b>	Township <b>T29N</b>	Range <b>08W</b>	Feet from the <b>880'</b>	North/South Line <b>FNL</b>	Feet from the <b>1170'</b>	East/West Line <b>FWL</b>	County <b>San Juan</b>
-------------------------	----------------------	-------------------------	---------------------	------------------------------	--------------------------------	-------------------------------	------------------------------	---------------------------

Latitude **36.687259** Longitude **-107.66847**

**NATURE OF RELEASE**

Type of Release <b>Produced Water</b>	Volume of Release <b>19 bbl</b>	Volume Recovered <b>18 bbl</b>
Source of Release <b>Pit tank – Corrosion</b>	Date and Hour of Occurrence <b>Unknown</b>	Date and Hour of Discovery <b>3/19/17 3:04 p.m.</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**OIL CONS. DIV DIST. 3**  
**JUL 05 2017**

If a Watercourse was Impacted, Describe Fully.\*

**N/A**



Describe Cause of Problem and Remedial Action Taken.\*

**Water discovered in cribbing of pit tank and pulled fluid in cribbing exposing hole in pit tank. Removed all fluid from pit & cribbing. Shut in well.**

Describe Area Affected and Cleanup Action Taken.\*

**ConocoPhillips inspected cribbing area and found it fully lined and sealed exposing no soil to contamination. Pit tank was repaired in place. No further work is required.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Lisa Hunter</b>	Approved by Environmental Specialist: 	
Title: <b>Field Environmental Specialist</b>	Approval Date: <b>8/10/2017</b>	Expiration Date:
E-mail Address: <b>Lisa.Hunter@cop.com</b>	Conditions of Approval:	Attached <input type="checkbox"/>
Date: <b>June 29, 2017</b> Phone: <b>(505) 258-1607</b>		

\* Attach Additional Sheets If Necessary

**NF1708736692**