



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

AUG 10 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-13-17 Operator: Enervest Operating, LLC API #30-039-23497

Property Name Candado Well No. 1E Location: Unit J Section 15 Township 26N Range 7W

Well Status(Shut-In or Producing) Initial PSI: Tubing 0 Intermediate — Casing 60 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>—</u>	<u>60</u>		
10 min	<u>0</u>	<u>—</u>	<u>60</u>		
15 min	<u>0</u>	<u>—</u>	<u>60</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>✓</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR — FRESH — SALTY — SULFUR — BLACK —

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE —

REMARKS:

No psi on Bradenhead

By Jason Chenover, Jan 15

Witness —

operator
(Position)

E-mail address JChenover@enervest.net