



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

AUG 15 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8-15-17 Operator Hilcom Drilling/Leases API #30-0 39-23501
Property Name: San Juan 306 Unit Well No. 1124 Location: Unit 26 Section 26 Township 30 Range 6
Well Status(Shut-In or Producing) Initial PSI: 1925 Tubing 0 Intermediate 0 Casing -2 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	-2	0	-3
10 min	0	0	-2	0	-3
15 min	0	0	-2	0	-3
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		/
Nothing	/	
Gas		/
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

BH - Nothing when opened - Nothing
when opened after 5 min shut in - Int. Med/Light
flow when opened - to dead at 1.25 min - Nothing

By Luis S. Jaquez
SWD
(Position)

Witness Monica Kuchling
when opened after 5 min shut in

E-mail address _____