



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

OIL CONS. DIV DIST. 3

AUG 09 2017

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 6-21-17 Operator BP America Production Company API # 3004522463

Property Name NEIL A 007A-PC/MV Location: Unit D Section 33 Township 32 Range 11
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 26.8 Intermediate N/A Casing 118.0 Bradenhead 113.9

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	Ø	117.9	N/A	N/A	N/A	Steady Flow	1m 45sec
10 minutes	Ø	117.9				Surges	
15 minutes	Ø	118.0				Down to Nothing	22 sec
20 minutes						No Flow	nothing after
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear _____ Fresh _____ Salty _____ Sulfur _____ Black _____

5 Minute Shut-in Bradenhead 0.9 Intermediate N/A

REMARKS:

Took samples on bradenhead, casing, + ~~the~~ tubing & compressor in recycle.

By Eugenia Hamilton
Leadtech.

(Position)

Witness _____