



NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC, NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://www.emnrd.state.nm.us/ocd/>

OIL CONS. DIV DIST. 3

AUG 09 2017

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 07/12/2017 Operator BP America Production Company API # 3004523425

Property Name LINDSEY B 001-DK Location: Unit M Section 28 Township 30 Range 9
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing 105.9psi Intermediate N/A Casing 116.9psi Bradenhead 22.9

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate			Bradenhead	Intermediate
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor		Flowed	Flowed
5 minutes	<u>Ø psi</u>	<u>125.8psi</u>	<u>N/A</u>	<u>N/A</u>	<u>N/A</u>	Steady Flow		<u>N/A</u>
10 minutes	<u>Ø psi</u>	<u>127.5psi</u>				Surges		
15 minutes	<u>Ø psi</u>	<u>112.6psi</u>				Down to Nothing	<u>4 sec to Ø psi</u>	
20 minutes	<u>Ø psi</u>	<u>107.3psi</u>				No Flow		
25 minutes	<u>Ø psi</u>	<u>104.1psi</u>				Gas		
30 minutes	<u>Ø psi</u>	<u>103.1psi</u>				Gas and Water		
5 minute SI	<u>1.2 psi</u>	<u>105.2psi</u>				Water		

If bradenhead flowed water, check all of the descriptions that apply below:

Clear Fresh Salty Sulfur Black

5 Minute Shut-in Bradenhead 1.2psi Intermediate N/A

REMARKS:

No compressor on location. Casing closed. Pulled gas samples from all strings
Tubing, Bradenhead, and Casing. Well started flowing 12 minutes into testing of
Bradenhead.

By Matthew Yarnie Witness
Desco Field Tech
(Position)