



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

OIL CONS. DIV DIST. 3

AUG 09 2017

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4/11/2017 Operator BP America API # 30-045 26 335

Property Name Chugge Canyon Unit Well No. 2425-D Location: Unit P Section 3 Township 27^N Range 12^W

Well Status (Shut In or Producing) Initial PSI: Tubing 11 Intermediate Casing 9 Bradenhead 22

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead	INTERM			
	BH	Int	Csg	Int	Csg
TIME	4	N/A	9		
5 min		N/A	9		
10 min	1	N/A	9		
15 min	0	N/A	9		
20 min		N/A			
25 min		N/A			
30 min		N/A			

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	N/A
Surges	N/A
Down to Nothing <u>13 min</u>	N/A
Nothing	N/A
Gas	N/A
Gas & Water	N/A
Water	N/A

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: Blow down to zero 13 min

By Jerry McQuinn
Optimizer
(Position)

Witness

E-mail address jerry.mcquinn@bhp.com