



# NEW MEXICO ENERGY, MINERALS AND NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC, NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
<http://www.emnrd.state.nm.us/ocd/>

OIL CONS. DIV DIST. 3

AUG 09 2017

## BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 7.14.17 Operator BP America Production Company API # 3004526798

Property Name DAVIS 001-PC Location: Unit E Section 23 Township 32 Range 11  
(Well Name and Number)

Pressure (Shut-in or Producing) Tubing N/A Intermediate N/A Casing 9.8 Bradenhead 34.9

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Time	Bradenhead			Intermediate		Bradenhead Intermediate	
	BH Blowdown	Casing Monitor	Intermediate Monitor	Intermediate Blowdown	Casing Monitor	Flowed	Flowed
5 minutes	$\emptyset$	9.8	N/A	N/A	N/A	Steady Flow	1 min 20 sec N/A
10 minutes	$\emptyset$	9.7				Surges	
15 minutes	$\emptyset$	9.7				Down to Nothing	48 sec.
20 minutes						No Flow	nothing after
25 minutes						Gas	
30 minutes						Gas and Water	
5 minute SI						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

Clear \_\_\_\_\_ Fresh \_\_\_\_\_ Salty \_\_\_\_\_ Sulfur \_\_\_\_\_ Black \_\_\_\_\_

5 Minute Shut-in Bradenhead  $\emptyset$  Intermediate N/A

### REMARKS:

Took samples from bradenhead & casing, casing flowing, slim hole setup.

By Eugenia Hami Hon  
Lead Tech.

Witness \_\_\_\_\_

(Position)