<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District III
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources Department Oil Conservation Division

For temporary pits, below-grade tanks, and multi-well fluid management pits, submit to the appropriate NMOCD District Office.

For permanent pits submit to the Santa Fe Environmental Bureau office and provide a copy to the appropriate NMOCD District Office.

Form C-144 Revised June 6, 2013

1220 South St. Francis Dr. Santa Fe, NM 87505

Pit, Below-Grade Tank, or
Proposed Alternative Method Permit or Closure Plan Application
Type of action: Below grade tank registration Permit of a pit or proposed alternative method Closure of a pit, below-grade tank, or proposed alternative method Modification to an existing permit/or registration Closure plan only submitted for an existing permitted or non-permitted pit, below-grade tank, or proposed alternative method
Instructions: Please submit one application (Form C-144) per individual pit, below-grade tank or alternative request
Please be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.
Operator: BP America Production Company OGRID #: 778
Address: 200 Energy Court, Farmington, NM 87401
Facility or well name: TAPP #4
API Number: 3004523967 OCD Permit Number:
U/L or Qtr/Qtr M Section 15 Township 28N Range 8W County: San Juan
Center of Proposed Design: Latitude 36.65696 Longitude -107.67425 NAD: □1927 ☑ 1983
Surface Owner: Federal State Tribal Trust or Indian Allotment
Pit: Subsection F, G or J of 19.15.17.11 NMAC
Liner Seams: Welded Factory Other Volume: bbl Dimensions: L x W x D
3,
∑ Below-grade tank: Subsection I of 19.15.17.11 NMAC ∑ANK B
Volume: 21 bbl Type of fluid: Produced water
Tank Construction material: Steel
☐ Secondary containment with leak detection ☐ Visible sidewalls, liner, 6-inch lift and automatic overflow shut-off
☐ Visible sidewalls and liner ☐ Visible sidewalls only ☐ Other <u>Single wall/ Double bottom; sidewalls visible</u>
Liner type: Thicknessmil
4. Alternative Method: Submittal of an exception request is required. Exceptions must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.

Fencing: Subsection D of 19.15.17.11 NMAC (Applies to permanent pits, temporary pits, and below-grade tanks) Chain link, six feet in height, two strands of barbed wire at top (Required if located within 1000 feet of a permanent residence, school, institution or church) Four foot height, four strands of barbed wire evenly spaced between one and four feet	hospital,
☐ Alternate. Please specify	
Alternate. Flease specify	
Netting: Subsection E of 19.15.17.11 NMAC (Applies to permanent pits and permanent open top tanks) Screen Netting Other	
☐ Monthly inspections (If netting or screening is not physically feasible)	
Signs: Subsection C of 19.15.17.11 NMAC	
12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers	
Signed in compliance with 19.15.16.8 NMAC	
Nariances and Exceptions: Justifications and/or demonstrations of equivalency are required. Please refer to 19.15.17 NMAC for guidance. Please check a box if one or more of the following is requested, if not leave blank: □ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. □ Exception(s): Requests must be submitted to the Santa Fe Environmental Bureau office for consideration of approval.	
9. Siting Criteria (regarding permitting): 19.15.17.10 NMAC Instructions: The applicant must demonstrate compliance for each siting criteria below in the application. Recommendations of acceptance are provided below. Siting criteria does not apply to drying pads or above-grade tanks.	ptable source
General siting	
Ground water is less than 25 feet below the bottom of a low chloride temporary pit or below-grade tank. - □ NM Office of the State Engineer - iWATERS database search; □ USGS; □ Data obtained from nearby wells	Yes No
Ground water is less than 50 feet below the bottom of a Temporary pit, permanent pit, or Multi-Well Fluid Management pit. NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	Yes No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended. (Does not apply to below grade tanks) - Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No
Within the area overlying a subsurface mine. (Does not apply to below grade tanks) - Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No
 Within an unstable area. (Does not apply to below grade tanks) Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; Topographic map 	☐ Yes ☐ No
Within a 100-year floodplain. (Does not apply to below grade tanks) - FEMA map	☐ Yes ☐ No
Below Grade Tanks	
Within 100 feet of a continuously flowing watercourse, significant watercourse, lake bed, sinkhole, wetland or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 200 horizontal feet of a spring or a fresh water well used for public or livestock consumption;. - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Temporary Pit using Low Chloride Drilling Fluid (maximum chloride content 15,000 mg/liter)	
Within 100 feet of a continuously flowing watercourse, or any other significant watercourse or within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). (Applies to low chloride temporary pits.) - Topographic map; Visual inspection (certification) of the proposed site	Yes No

Within 300 feet from a occupied permanent residence, school, hospital, institution, or church in existence at the time of initial	Yes No
application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	
Within 200 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 300feet of any other fresh water well or spring, in existence at the time of the initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 100 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Temporary Pit Non-low chloride drilling fluid	
Within 300 feet of a continuously flowing watercourse, or any other significant watercourse, or within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).	
- Topographic map; Visual inspection (certification) of the proposed site	Yes No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
Within 500 horizontal feet of a spring or a private, domestic fresh water well used by less than five households for domestic or stock watering purposes, or 1000 feet of any other fresh water well or spring, in the existence at the time of the initial application; - NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet of a wetland US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Permanent Pit or Multi-Well Fluid Management Pit	
Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa	
lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of	
 initial application. NM Office of the State Engineer - iWATERS database search; Visual inspection (certification) of the proposed site 	☐ Yes ☐ No
Within 500 feet of a wetland. - US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Temporary Pits, Emergency Pits, and Below-grade Tanks Permit Application Attachment Checklist: Subsection B of 19.15.17.9 N Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the doc attached.	
Hydrogeologic Report (Below-grade Tanks) - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Hydrogeologic Data (Temporary and Emergency Pits) - based upon the requirements of Paragraph (2) of Subsection B of 19.15.17.9 Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC	NMAC
□ Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC □ Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC □ Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19. and 19.15.17.13 NMAC	15.17.9 NMAC
☐ Previously Approved Design (attach copy of design) API Number: or Permit Number:	
II.	
Multi-Well Fluid Management Pit Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the doc attached.	cuments are
 □ Design Plan - based upon the appropriate requirements of 19.15.17.11 NMAC □ Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC 	
☐ A List of wells with approved application for permit to drill associated with the pit. ☐ Closure Plan (Please complete Boxes 14 through 18, if applicable) - based upon the appropriate requirements of Subsection C of 19 and 19.15.17.13 NMAC	.15.17.9 NMAC
Hydrogeologic Data - based upon the requirements of Paragraph (4) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC	
Previously Approved Design (attach copy of design) API Number: or Permit Number:	

Permanent Pits Permit Application Checklist: Subsection B of 19.15.17.9 NMAC Instructions: Each of the following items must be attached to the application. Please indicate, by a check mark in the box, that the attached. Hydrogeologic Report - based upon the requirements of Paragraph (1) of Subsection B of 19.15.17.9 NMAC Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Climatological Factors Assessment Certified Engineering Design Plans - based upon the appropriate requirements of 19.15.17.11 NMAC Dike Protection and Structural Integrity Design - based upon the appropriate requirements of 19.15.17.11 NMAC Laak Detection Design - based upon the appropriate requirements of 19.15.17.11 NMAC Liner Specifications and Compatibility Assessment - based upon the appropriate requirements of 19.15.17.11 NMAC Quality Control/Quality Assurance Construction and Installation Plan Operating and Maintenance Plan - based upon the appropriate requirements of 19.15.17.12 NMAC Freeboard and Overtopping Prevention Plan - based upon the appropriate requirements of 19.15.17.11 NMAC Nuisance or Hazardous Odors, including H ₂ S, Prevention Plan Emergency Response Plan Oil Field Waste Stream Characterization Monitoring and Inspection Plan Erosion Control Plan Closure Plan - based upon the appropriate requirements of Subsection C of 19.15.17.9 NMAC and 19.15.17.13 NMAC	documents are
Proposed Closure: 19.15.17.13 NMAC	
Instructions: Please complete the applicable boxes, Boxes 14 through 18, in regards to the proposed closure plan. Type: Drilling Workover Emergency Cavitation P&A Permanent Pit Below-grade Tank Multi-well F Alternative Proposed Closure Method: Waste Excavation and Removal Waste Removal (Closed-loop systems only) On-site Closure Method (Only for temporary pits and closed-loop systems) In-place Burial On-site Trench Burial Alternative Closure Method	luid Management Pit
14.	
Waste Excavation and Removal Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be closure plan. Please indicate, by a check mark in the box, that the documents are attached. Protocols and Procedures - based upon the appropriate requirements of 19.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of Subsection C of 19.15.17.13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings) Soil Backfill and Cover Design Specifications - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC	
15.	
Siting Criteria (regarding on-site closure methods only): 19.15.17.10 NMAC Instructions: Each siting criteria requires a demonstration of compliance in the closure plan. Recommendations of acceptable sour provided below. Requests regarding changes to certain siting criteria require justifications and/or demonstrations of equivalency. F 19.15.17.10 NMAC for guidance.	rce material are Please refer to
Ground water is less than 25 feet below the bottom of the buried waste NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is between 25-50 feet below the bottom of the buried waste - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Ground water is more than 100 feet below the bottom of the buried waste. - NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells	☐ Yes ☐ No ☐ NA
Within 100 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark). - Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within 300 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application. - Visual inspection (certification) of the proposed site; Aerial photo; Satellite image	☐ Yes ☐ No
Within 300 horizontal feet of a private, domestic fresh water well or spring used for domestic or stock watering purposes, in existence at the time of initial application. - NM Office of the State Engineer - iWATERS database; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No
Within 300 feet of a wetland.	L 168 NO
US Fish and Wildlife Wetland Identification map; Topographic map; Visual inspection (certification) of the proposed site	☐ Yes ☐ No
Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance	

adopted pursuant to NMSA 1978, Section 3-27-3, as amended.	
- Written confirmation or verification from the municipality; Written approval obtained from the municipality	☐ Yes ☐ No
Within the area overlying a subsurface mine Written confirmation or verification or map from the NM EMNRD-Mining and Mineral Division	☐ Yes ☐ No
 Within an unstable area. Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geologic Society; Topographic map 	cal Yes No
Within a 100-year floodplain FEMA map	Yes No
On-Site Closure Plan Checklist: (19.15.17.13 NMAC) Instructions: Each of the following items must be attached to the close by a check mark in the box, that the documents are attached. Siting Criteria Compliance Demonstrations - based upon the appropriate requirements of 19.15.17.10 NMAC Proof of Surface Owner Notice - based upon the appropriate requirements of Subsection E of 19.15.17.13 NMAC Construction/Design Plan of Burial Trench (if applicable) based upon the appropriate requirements of Subsection K of 19. Construction/Design Plan of Temporary Pit (for in-place burial of a drying pad) - based upon the appropriate requirements of 19.15.17.13 NMAC Confirmation Sampling Plan (if applicable) - based upon the appropriate requirements of 19.15.17.13 NMAC Waste Material Sampling Plan - based upon the appropriate requirements of 19.15.17.13 NMAC Disposal Facility Name and Permit Number (for liquids, drilling fluids and drill cuttings or in case on-site closure standar Soil Cover Design - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Re-vegetation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC Site Reclamation Plan - based upon the appropriate requirements of Subsection H of 19.15.17.13 NMAC	9.15.17.11 NMAC s of 19.15.17.11 NMAC
Operator Application Certification: I hereby certify that the information submitted with this application is true, accurate and complete to the best of my knowledge and the complete to the best of my knowledge and the certification: Name (Print): Title:	
Signature: Date:	
Signature:	
e-mail address:	
e-mail address:	omitting the closure report.
e-mail address: Telephone:	omitting the closure report. e do not complete this

22. Operator Closure Certification:	
	itted with this closure report is true, accurate and complete to the best of my knowledge and licable closure requirements and conditions specified in the approved closure plan.
Name (Print): Steve Moskal	Title: Field Environmental Coordinator
Signature:	Date: <u>August 9, 2017</u>
e-mail address: steven.moskal@bp.com	Telephone: (505) 326-9497

BP AMERICA PRODUCTION COMPANY

SAN JUAN BASIN, NORTHWEST NEW MEXICO

BELOW-GRADE TANK CLOSURE PLAN

TAPP #4 (B) API No. 3004523967 Unit Letter M, Section 15, T28N, R8W

This plan will address the standard protocols and procedures for closure of below-grade tanks (BGTs) on BP America Production Company (BP) well sites. As stipulated in Paragraph A of 19.15.17.13 NMAC, BP shall close a BGT within the time periods provided in 19.15.17.13 NMAC, or by an earlier date that the New Mexico Oil Conservation Division (NMOCD) requires because of imminent danger to fresh water, public health, safety or the environment. If deviations from this plan are necessary, any specific changes will be included on form C-144 and approved by the NMOCD. BP shall close an existing BGT that does not meet the requirements of Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC or is not included in Paragraph (5) of Subsection I of 19.15.17.11 NMAC within five years after June 16, 2008, if not retrofit with a BGT that complies with the BP NMOCD approved BGT design attached to the BP Design and Construction Plan. BP shall close an existing BGT that does not meet the requirements of Paragraphs (1) through (4) of Subsection I of 19.15.17.11 NMAC, if not previously retrofitted to comply with the BP NMOCD approve BGT Design attached to the BP Design and Construction Plan, prior to any sale or change in operator pursuant to 19.15.9.9 NMAC. BP shall close the permitted BGT within 60 days of cessation of the BGTs operation or as required by the transitional provisions of Subsection B, D, or E of 19.15.17.17 NMAC.

General Closure Plan

- 1. BP shall notify the surface owner by certified mail that it plans to close a BGT. Evidence of mailing of the notice to the address of the surface owner shown in the county tax records demonstrates compliance with this requirement.

 Notice is attached.
- 2. BP shall notify the division District III office verbally or by other means at least 72 hours, but not more than one (1) week, prior to any closure operation. The notice shall include the operator's name, and the location to be closed by unit letter, section, township and range. If the BGT closure is associated with a particular well, then the notice shall also include the well's name, number and API number.
 - Notice was provided and is attached.
- 3. BP shall remove liquids and sludge from the BGT prior to implementing a closure method and dispose of the liquids and sludge in a NMOCD's division-approved facility. The facilities to be used are:
 - a. BP Crouch Mesa Landfarm, Permit NM-02-003 (Solids)
 - b. JFJ Landfarm, Permit NM-01-010(B) (Solids and Sludge)
 - c. Basin Disposal, Permit NM-01-0005 (Liquids)
 - Envirotech Inc Soil Remediation Facility, Permit NM-01-0011 (Solids and Sludge)
 - e. BP Operated E.E. Elliott SWD #1, API 30-045-27799 (Liquids)

- f. BP Operated 13 GCU SWD #1, API 30-045-28601 (Liquids)
- g. BP Operated GCU 259 SWD, API 30-045-20006 (Liquids)
- h. BP Operated GCU 306 SWD, API 30-045-24286 (Liquids)
- i. BP Operated GCU 307 SWD, API 30-045-24248 (Liquids)
- j. BP Operated GCU 328 SWD, API 30-045-24735 (Liquids)
- k. BP Operated Pritchard SWD #1, API 30-045-28351 (Liquids)

All liquids and sludge in the BGT were removed and sent to one of the above NMOCD approved facilities for disposal.

4. BP shall remove the BGT and dispose of it in a NMOCD approved facility or recycle, reuse, or reclaim it in a manner that the NMOCD approves. If a liner is present and must be disposed of it will be cleaned by scraping any soils or other attached materials on the liner to a de minimus amount and disposed at a permitted solid waste facility, pursuant to Subparagraph (m) of Paragraph (1) of Subsection C of 19.15.35.8 NMAC. Documentation as to the final disposition of the removed BGT will be provided in the final closure report.

The BGT was transported for recycling.

5. BP shall remove any on-site equipment associated with a BGT unless the equipment is required for well production.

All equipment associated with the BGT has been removed.

6. BP shall test the soils beneath the BGT to determine whether a release has occurred. BP shall collect at a minimum: a five (5) point composite sample and individual grab samples from any area that is wet, discolored or showing other evidence of a release and analyze for BTEX, TPH and chlorides. The testing methods for those constituents are as follows;

Constituents	Testing Method	Release Verification	Sample
	21 bbl BGT	(mg/Kg)	results
Benzene	US EPA Method SW-846 8021B or 8260B	10	< 0.022
Total BTEX	US EPA Method SW-846 8021B or 8260B	50	< 0.087
TPH	US EPA Method SW-846 418.1 or 8015 extended	100	<u><51</u>
Chlorides	US EPA Method 300.0 or 4500B	620	<30

Notes: mg/Kg = milligram per kilogram, BTEX = benzene, toluene, ethylbenzene, and total xylenes, TPH = total petroleum hydrocarbons. Other EPA methods that the division approves may be applied to all constituents listed. Chloride closure standards will be determined by which ever concentration level is greatest.

Soil under the BGT was sampled for chloride, TPH and BTEX with all concentrations below the stated limits. The field report and laboratory reports are attached.

7. BP shall notify the division District III office of its results on form C-141. **C-141 is attached.**

- 8. If it is determined that a release has occurred, then BP will comply with 19.15.30 NMAC and 19.15.29 NMAC, as appropriate.

 Sampling results indicate a release has not occurred. Attached is a laboratory report and C-141.
- 9. If the sampling demonstrates that a release has not occurred or that any release does not exceed the concentrations specified above, then BP shall backfill the excavation, with compacted, non-waste containing, earthen material; construct a division-prescribed soil cover, re-contour and re-vegetate the location. The location will be reclaimed if it is not with in the active process area

Sampling results indicate a release has not occurred. Attached is a laboratory report and field report.

10. BP shall reclaim the BGT location and all areas associated with the BGT including associated access roads to a safe and stable condition that blends with the surrounding undisturbed area. BP shall substantially restore the impacted surface area to the condition that existed prior to oil and gas operations by placement of the soil cover as provided in Subsection H of 19.15.17.13 NMAC, re-contour the location and associated areas to a contour that approximates the original contour and blends with the surrounding topography and re-vegetate according to Subsection I of 19.15.17.13 NMAC.

The area has been backfilled and will be reclaimed once the well is plugged and abandoned.

11. The soil cover for closures where the BGT has been removed or remediated to the NMOCD's satisfaction shall consist of the background thickness of topsoil or one foot of suitable material to establish vegetation at the site, whichever is greater. The soil cover will be constructed to the site's existing grade and all practicable efforts will be made to prevent ponding of water and erosion of the cover material.

The area has been backfilled and will be reclaimed once the well is plugged and abandoned.

12. BP shall seed the disturbed area the first growing season after closure of the BGT. Seeding will be accomplished by drilling on the contour whenever practical or by other division-approved methods. Vegetative cover will be, at a minimum, 70% of the native perennial vegetative cover (un-impacted by overgrazing, fire or other intrusion damaging to native vegetation), consisting of at least three native plant species, including at least one grass, but not including noxious weeds, and maintenance of that cover through two successive growing seasons. During the two growing seasons that prove viability, there shall be no artificial irrigation of the vegetation.

The area has been backfilled and will be reclaimed once the well is plugged and abandoned.

13. BP shall seed, plant and re-seed pursuant to Paragraph (3) of Subsection I of 19.15.17.13 NMAC, until the location successfully achieves the required vegetative cover.

The area has been backfilled and will be reclaimed once the well is plugged and abandoned.

14. Pursuant to Paragraph (5) of Subsection I of 19.15.17.13 NMAC, BP shall notify the NMOCD when it has seeded or planted and when it successfully achieves revegetation.

The area has been backfilled and will be reclaimed once the well is plugged and abandoned.

- 15. Within 60 days of closure completion, BP shall submit a closure report on NMOCD's form C-144, and will include the following;
 - a. proof of closure notification (surface owner and NMOCD)
 - b. sampling analytical reports; information required by 19.15.17 NMAC;
 - c. disposal facility name and permit number
 - d. details on back-filling, capping, covering, and where applicable re-vegetation application rates and seeding techniques and
 - e. site reclamation, photo documentation.

 BP did not meet the 60 closure completion requirement due to an error in internal tracking. Closure report on C-144 form is included including photos of reclamation completion.
- 16. BP shall certify that all information in the report and attachments is accurate, truthful, and compliant with all applicable closure requirements and conditions specified in the approved closure plan.

Certification section of C-144 has been completed.

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Revised August 8, 2011

Form C-141

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

			Rele	ease Notific	catio	n and Co	orrective A	ction					
						OPERA	ГOR		itia	l Report Final Repo			
Name of Co	ompany: B	P				Contact: Ste	eve Moskal						
Address: 20	00 Energy	Court, Farmi	ngton, N	M 87401		Telephone No.: 505-326-9497							
Facility Na	me: Tapp #	‡ 4				Facility Type: Natural gas well							
Surface Ow	ner: Feder	al		Mineral C)wner:	Federal		API	No.	3004523967			
				LOCA	TIO	N OF RE	LEASE						
Unit Letter M	Section 15	Township 28N	Range 8W	Feet from the 1,045	North	/South Line	Feet from the 790	East/West Lin West	ie	County: San Juan			
			La	titude 36.65	696°	Longitu	de -107.674	125°					
						OF REL	EASE						
Type of Rele	ase: none				UTUS			vn Volun	ne Re	ecovered: N/A			
Source of Re	lease: below	v grade tank –	21 bbl				Hour of Occurrence	ce: Date a	nd F	Hour of Discovery: none			
Was Immedi	ate Notice (Given?					Whom?						
			Yes 🛚	No Not Re	equired								
-													
Was a Water	course Read		Yes 🗵	No		If YES, Vo	olume Impacting t	the Watercourse					
If a Watercon	ırse was Im	pacted, Descr	ibe Fully.	k									
									al.	Soil analysis resulted for			
Chlorides, B	TEX, and T	PH below BG	T closure	standards. Field	reports	and laborator	y results are attac	hed.					
Describe Are	a Affected	and Cleanup A	Action Tak	cen.* No action no	ecessary	y. Final labor	atory analysis dete	ermined no rem	edial	action is required.			
Name of Company: BP Address: 200 Energy Court, Farmington, NM 87401 Facility Name: Tapp #4 Surface Owner: Federal Mineral Owner: Federal API No. 3004523967 LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County: San Juan													
				tance of a C 141	report	ioes not renev	e the operator or	responsibility it	1 00	impliance with any other			
							OIL CON	SERVATIO	NI	DIVISION			
Signature:	Abus 11	Mu)											
Printed Name	e: Steve Mo	skal				Approved by	Environmental S	pecialist:		9			
Title: Field F	Invironment	al Coordinato	r			Approval Da	te:	Expirati	on D	Pate:			
E-mail Addre	ess: steven.r	moskal@bp.co	om			Conditions of	Approval:			Attached			
Datas Assess	+0.2017		Dhone: 4	205 226 0407						Anacheu 🔲			
Date: Augus	19, 2017		Phone: 3	003-320-949/									

^{*} Attach Additional Sheets If Necessary

bp



BP America Production Company 200 Energy Court Farmington, NM 87401

May 19, 2017

Bureau of Land Management Whitney Thomas 6251 College Suite A Farmington, NM 87402

VIA EMAIL

Re: Notification of plans to close/remove a below grade tank

Well Name: TAPP 004 API #: 3004523967

Dear Mrs. Thomas,

As part of the NM "Pit Rule": 19.15.17.13 Closure Requirements, Paragraph J. BP America Production Company (BP) is required to notify the surface owner of BP's plans to close/remove a below grade tank. BP wishes to inform you of our plans to close/remove the below grade tank on its well pad located on your surface. BP plans to commence this work on or about May 25, 2017. If there aren't any unforeseen problems, the work should be completed within 10 working days.

As a point of clarification, BP will be closing the below grade tank and either operating without one or replacing it with an above ground tank, the well site will continue to operate.

If witnessing of the tank removal is required please contact me for a specific time (505)-326-9497.

Sincerely,

Steven Moskal

BP America Production Company

Moskal, Steven

From:

Moskal, Steven

Sent:

Wednesday, May 24, 2017 4:52 PM

To:

Fields, Vanessa, EMNRD (Vanessa.Fields@state.nm.us); Smith, Cory, EMNRD; Whitney Thomas

Cc:

jeffcblagg@aol.com; blagg_njv@yahoo.com; Powell, Ross L (MBF SERVICES)

Subject:

Re: BP Pit Close Notification - TAPP 004

The BGT closure is scheduled for 2:00 PM tomorrow.

Thank you,

Steve Moskal Environmental Coordinator -BP- SJS (505) 330-9179 Sent from my mobile device

On May 19, 2017, at 9:32 AM, Buckley, Farrah (CH2M HILL) < farrah.buckley@bp.com > wrote:

BP America Production Company

200 Energy Court Farmington, NM 87401 Phone: (505) 326-9200

SENT VIA E-MAIL TO: CORY.SMITH@STATE.NM.US; VANESSA.FIELDS@STATE.NM.US

May 19, 2017

New Mexico Oil Conservation Division 1000 Rio Brazos Road Aztec, New Mexico 87410

RE: Notice of Proposed Below-Grade Tank (BGT) Closure

TAPP 004 API 30-045-23967 (M) Section 15 – T28N – R08W San Juan County, New Mexico

Dear Mr. Cory Smith and Mrs. Vanessa Fields,

In regards to the captioned subject and requirements of the NMOCD pit rule, this letter is notification that BP is planning to close a 95bbl BGT and a 21bbl BGT that will no longer be operational at this well site. We anticipate this work to start on or around May 25, 2017.

Should you have any questions, please feel free to contact BP at our Farmington office.

Sincerely,

Steven Moskal BP Field Environmental Coordinator

(505) 326-9497

Farrah Buckley
BGT Project Support
970-946-9199 -cell

This email and any attachments are intended only for the addressee(s) listed above and may contain confidential, proprietary, and/or privileged information. If you are not an intended recipient, please immediately advise the sender by return email, delete this email and any attachments, and destroy any copies of same. Any unauthorized review, use, copying disclosure or distribution of this email and any attachments is prohibited.

CLIENT: BP	P.O. BOX 87, I	ENGINEERING BLOOMFIELD, 05) 632-1199		API #: 3004523 TANK ID (if applicble): B	967
FIELD REPORT:	(circle one): BGT CONFIRMATION	/ RELEASE INVESTIGATIO	N / OTHER:	PAGE #: 1 of	_1_
SITE INFORMATION	: SITE NAME: TAPP	#4		DATE STARTED: 05/2	5/17
QUAD/UNIT: M SEC: 15 TWP:	28N RNG: 8W PM	M: NM CNTY:	SJ ST: NM	DATE FINISHED:	
1/4-1/4/FOOTAGE: 1,045'S / 790	D'W SW/SW LEASE	TYPE: FEDERAL/ST	TATE / FEE / INDIAN	ENVIRONMENTAL	
LEASE #: SF078499	PROD. FORMATION: MV/DK	CONTRACTOR: MBF	KE - R. POWELL	SPECIALIST(S):	JV
REFERENCE POINT	: WELL HEAD (W.H.) GF	PS COORD.: 36.0	65698 X 107.67469	GL ELEV.: 5,	870'
1) 21 BGT (SW/DB) - B	GPS COORD.:	6.65696 X 107.674	25 DISTANCE/BE	ARING FROM W.H.: 133', S	84E
2)	GPS COORD.:		DISTANCE/BE/	ARING FROM W.H.:	
3)	GPS COORD.:		DISTANCE/BE/	ARING FROM W.H.:	
4)				ARING FROM W.H.:	OVM
SAMPLING DATA:					READING (ppm)
1) SAMPLE ID:	-			5B/8021B/300.0 (CI)	NA
SAMPLE ID:					
	SAMPLE DATE:				
5) SAMPLE ID:	SAMPLE DATE:	SAMPLE TIME:	LAB ANALYSIS:		
SOIL COLOR: DARK YEL COHESION (ALL OTHERS): NON COHESIVE SLIGHTLY CONSISTENCY (NON COHESIVE SOILS): LC MOISTURE: DRY SLIGHTLY MOIST MOIST / M SAMPLE TYPE: GRAB COMPOSITE # DISCOLORATION/STAINING OBSERVED: YES N SITE OBSERVATION APPARENT EVIDENCE OF A RELEASE OBSERVE EQUIPMENT SET OVER RECLAIMED AREA:	COHESIVE / COHESIVE / HIGHLY COHESIVE / OSE FIRM DENSE / VERY DENSE TO STURATED TO STURATED	DENSITY (COHESIVE CLE HC ODOR DETECTED: YES ANY AREAS DISPLAYING V NT: YES NO EXPLANATION-	AYS & SILTS): SOFT / FIRM AS NO EXPLANATION -		Y PLASTIC
OTHER: NMOCD OR BLM NOT PRESENT	NA ft. X NA		t. EXCAVATION ES	TIMATION (Cubic Yards) :	NA
	EAREST WATER SOURCE: >1,00			CD TPH CLOSURE STD:	
SITE SKETCH [BGT Located : off on s	PLOT PLAN WOODEN R.W.	N TIM	I CALIB. READ. = NA ppn I CALIB. GAS = NA ppn E: NA am/pm DATE: MISCELL. NOT	NA
	FENCE	BERM (21)-B PBGTL T.B. ~6' B.G.	F N TO	REF #: P-850 ID: VHIXONEVB2 IJ #: ermit date(s): 06/14 ICD Appr. date(s): 04/18 ICD Appr. date(s): 04/18 ICD Appr. date(s): 04/18 BGT Sidewalls Visible: Y / N BGT Sidewalls Visible: Y / N	1/10 1/17 1/17
NOTES: BGT = BELOW-GRADE TANK; E.D. = EXCAVATIC T.B. = TANK BOTTOM; PBGTL = PREVIOUS BEL APPLICABLE OR NOT AVAILABLE; SW - SINGLE NOTES: GOOGLE EARTH IMAGE	OW-GRADE TANK LOCATION; SPD = SAMPLI WALL; DW - DOUBLE WALL; SB - SINGLE B	E POINT DESIGNATION; R.W. = RET	PPROX.; W.H. = WELL HEAD; TAINING WALL; NA - NOT	BGT Sidewalls Visible: Y / Magnetic declination: 10	

Analytical Report

Lab Order 1705D56

Date Reported: 5/31/2017

Hall Environmental Analysis Laboratory, Inc.

CLIENT: Blagg Engineering

Client Sample ID: 5PC-TB @ 6'(21)-B

Project:

TAPP#4

Collection Date: 5/25/2017 2:15:00 PM

Lab ID: 1705D56-002 Matrix: MEOH (SOIL)

Received Date: 5/26/2017 7:50:00 AM

Analyses	Result	PQL Qu	al Units	DF	Date Analyzed	Batch
EPA METHOD 300.0: ANIONS					Analyst	MRA
Chloride	ND	30	mg/Kg	20	5/26/2017 11:16:14 AM	31989
EPA METHOD 8015M/D: DIESEL RANG	E ORGANICS	3			Analyst	TOM
Diesel Range Organics (DRO)	ND	10	mg/Kg	1	5/26/2017 11:10:37 AM	31984
Motor Oil Range Organics (MRO)	ND	51	mg/Kg	1	5/26/2017 11:10:37 AM	31984
Surr: DNOP	84.0	70-130	%Rec	1	5/26/2017 11:10:37 AM	31984
EPA METHOD 8015D: GASOLINE RANG	SE .				Analyst	NSB
Gasoline Range Organics (GRO)	ND	4.4	mg/Kg	1	5/26/2017 12:57:49 PM	R43104
Surr: BFB	99.1	54-150	%Rec	1	5/26/2017 12:57:49 PM	R43104
EPA METHOD 8021B: VOLATILES					Analyst	NSB
Benzene	ND	0.022	mg/Kg	1	5/26/2017 12:57:49 PM	B43104
Toluene	ND	0.044	mg/Kg	1	5/26/2017 12:57:49 PM	B43104
Ethylbenzene	ND	0.044	mg/Kg	1	5/26/2017 12:57:49 PM	B43104
Xylenes, Total	ND	0.087	mg/Kg	1	5/26/2017 12:57:49 PM	B43104
Surr: 4-Bromofluorobenzene	117	66.6-132	%Rec	1	5/26/2017 12:57:49 PM	B43104

Refer to the QC Summary report and sample login checklist for flagged QC data and preservation information.

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- RPD outside accepted recovery limits
- % Recovery outside of range due to dilution or matrix
- B Analyte detected in the associated Method Blank
- E Value above quantitation range
- Analyte detected below quantitation limits Page 2 of 6 J
- Sample pH Not In Range P
- Reporting Detection Limit
- Sample container temperature is out of limit as specified

5/25/17	S/25//2							5/25/17	referie		Date	□ EDD (Type)	D NELAP	Accreditation:	QA/QC Package	email or Fax#;	Phone #:		Mailing Address:		Client	2
I'me	1536							2141	1400		Time	ype)		tion:	ard	ax#:			ddress:		BLAG	- IIIDI
samples submitt	Relinquished by							SOIL	Tion		Matrix		□ Other				(505) 632-1199	BLOOM	P.O. BOX 87		G ENGR.	J-Cu:
Co Contracted to other accredited laboratories. This serves as notice of this possibility. Any sub-contracted data will be clearly notated on the analytical report.	No.							5PC-TB@ 6 '(ZI)+B	or treat of the same		Sample Request ID				Level 4 (Full Validation)		2-1199	BLOOMFIELD, NM 87413	X87		BLAGG ENGR. / BP AMERICA	Clidill-Ol-Custony Necola
bcontracted to other	MOLD \$1							4021	4 04-1	Type and #	Container	Sample Temperature:	On lice:	Sampler:		Project Manager:		Project #:		Project Name:	☐ Standard	The state of the s
accredited laboratorie	while							Cool	COO	Type	Preservative	erature: \	N Yes	NELSON VELEZ	NELSON VELEZ	ger			TAPP #4	1	☑ Rush	1
5 726 17 0750	1							-007	100	1765056	HEAL No.	2000	□ No	ELEZ NY	ELEZ				45	1	DAY	SAME
Ref	Rem							4	4	BTEX	+ MT	BE +	TM	D's (8021B)					1		_
Reference #	Remarks: BILL DIRECTLY TO BP & REFERENCE # WHE CONTACT: STEVE MOSKAL					it	1							-	s only)	1		Tel	490			
VID: V	9		-					<	4	-		_			/MRO)	0		Tel. 505-345-3975	4901 Hawkins NE -			
W Sub-	REFE		+						+		(Met		-	_		_		-34	wkir	4	>	I
P - 850	RECTL						-		+		(Met		100-		eni			-39	N SC	WW	ξ	HA
O acted	SKAI				-1-				-	The same	(8310	the Merce	-	OSH	/IS)		An	75		hall	5	
lata yii	EN A	(2.5	-		+				+	-	M 8 A	-	_	NO.	PO, SO	1	Analysis	Fan	Mbu	envi	S	Z
De c	BILL DIRECTLY TO BP USING THE CONTAC & REFERENCE # WHEN APPLICABLE STEVE MOSKAL / VANCE HIXON		-				-			-		-	_		2 PCB's	-	is R	Fax 505-345-4107	quer	www.hallenvironmental.com	S	5
early	ABLE		1		1 1		-		-		B (VC		10.1	0.00	21003		Request	5-34	que,	nent	5	N
otate	ON		+				+			1 100	(Sen	_	(AC				ist	5-41	Z	al.co	BC	ž
gn lbs	BILL DIRECTLY TO BP USING THE CONTACT WITH CORRESPONDING VID & REFERENCE # WHEN APPLICABLE: STEVE MOSKAL / VANCE HIXON		1					<	4				_	-	ater - 300	0.1)		07	Albuquerque, NM 87109	ä	ALYSIS LABORATORY	ENVIRONMENTAL
analy	CORRE																		9		4	Z
ical re	SPON		1/-	7 1						Grab	sam	ple									유	7
Pon.	DING							<	4	5 pt.	comp	posit	e si	amp	le						3	-
	VID									Air B	ubble	SIYO	or N)								

Chain-of-Custody Record

lum-Around time:

Hall Environmental Analysis Laboratory, Inc.

WO#:

1705D56

31-May-17

Client:

Blagg Engineering

Project:

TAPP #4

Sample ID MB-31989

SampType: MBLK

TestCode: EPA Method 300.0: Anions

Client ID:

PBS

Batch ID: 31989

PQL

PQL

1.5

RunNo: 43101

Prep Date: 5/26/2017

Sample ID LCS-31989

Analysis Date: 5/26/2017

SeqNo: 1356922

Units: mg/Kg

Qual

Analyte

Result

ND

SPK value SPK Ref Val %REC LowLimit

HighLimit

RPDLimit %RPD

Chloride

SampType: LCS Batch ID: 31989

RunNo: 43101

TestCode: EPA Method 300.0: Anions

LowLimit

Client ID: Prep Date:

5/26/2017

LCSS

Analysis Date: 5/26/2017

SeqNo: 1356923

Units: mg/Kg

%RPD **RPDLimit**

Qual

SPK value SPK Ref Val

%REC

HighLimit

Chloride

Analyte

Result 14

110

95.6 90 1.5 15.00

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- Holding times for preparation or analysis exceeded H
- Not Detected at the Reporting Limit ND
- R RPD outside accepted recovery limits S % Recovery outside of range due to dilution or matrix
- В Analyte detected in the associated Method Blank
- E Analyte detected below quantitation limits I
- P Sample pH Not In Range
- Reporting Detection Limit RL Sample container temperature is out of limit as specified
- Value above quantitation range
 - Page 3 of 6

Hall Environmental Analysis Laboratory, Inc.

WO#:

1705D56

31-May-17

Client:

Blagg Engineering

Project:

TAPP #4

Sample ID LCS-31984	SampType: LCS TestCode: EPA Method 8015M/D: Diesel Range Organics									
Client ID: LCSS	Batch ID: 31984 RunNo: 43088									
Prep Date: 5/26/2017	Analysis Da	ate: 5/	26/2017	S	eqNo: 1	356258	Units: mg/k	(g		
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Diesel Range Organics (DRO)	40	10	50.00	0	79.4	73.2	114			
Surr: DNOP	4.4		5.000		87.8	70	130			

Sample ID MB-31984	SampType: MBLK			Tes						
Client ID: PBS	Batch ID: 31984			R	RunNo: 43088					
Prep Date: 5/26/2017	Analysis Date: 5/26/2017			SeqNo: 1356259			Units: mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Diesel Range Organics (DRO)	ND	10								
Motor Oil Range Organics (MRO)	ND	50								
Surr: DNOP	9.3		10.00		93.3	70	130			

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- Sample Diluted Due to Matrix D
- Η Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- % Recovery outside of range due to dilution or matrix
- В Analyte detected in the associated Method Blank
- J Analyte detected below quantitation limits
 - Sample pH Not In Range
- RL Reporting Detection Limit

P

Sample container temperature is out of limit as specified

E Value above quantitation range

Page 4 of 6

Hall Environmental Analysis Laboratory, Inc.

WO#:

1705D56

31-May-17

Client:

Blagg Engineering

Project:

TAPP #4

Sample ID 2.5UG GRO LCS	SampType:	LCS	TestCode: EPA Method 8015D: Gasoline Range						
Client ID: LCSS	Batch ID:	R43104	RunNo: 43104						
Prep Date:	Analysis Date:	SeqNo: 1356843			Units: mg/Kg				
Analyte	Result PQ	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Gasoline Range Organics (GRO)	24 5	.0 25.00	0	96.4	76.4	125			
Surr: BFB	1100	1000		112	54	150			

Sample ID RB	SampT	уре: МЕ	BLK	TestCode: EPA Method 8015D: Gasoline Range						
Client ID: PBS	Batch ID: R43104			RunNo: 43104						
Prep Date:	Analysis D	ate: 5/	26/2017	S	eqNo: 1	356846	Units: mg/K	(g		
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual
Gasoline Range Organics (GRO)	ND	5.0								
Surr: BFB	990		1000		99.4	54	150			

Qualifiers:

* Value exceeds Maximum Contaminant Level.

D Sample Diluted Due to Matrix

H Holding times for preparation or analysis exceeded

ND Not Detected at the Reporting Limit

R RPD outside accepted recovery limits

S % Recovery outside of range due to dilution or matrix

B Analyte detected in the associated Method Blank

E Value above quantitation range

J Analyte detected below quantitation limits

Page 5 of 6

P Sample pH Not In Range

RL Reporting Detection Limit

W Sample container temperature is out of limit as specified

Hall Environmental Analysis Laboratory, Inc.

WO#:

1705D56

31-May-17

Client:

Blagg Engineering

Project:

TAPP #4

Sample ID 100NG BTEX LO	CS SampT	ype: LC	S	Tes	tCode: E							
Client ID: LCSS	Batch	Batch ID: B43104			RunNo: 43104							
Prep Date:	Analysis D	Analysis Date: 5/26/2017			SeqNo: 1	356851	Units: mg/Kg					
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual		
Benzene	1.0	0.025	1.000	0	102	80	120					
Toluene	1.0	0.050	1.000	0	102	80	120					
Ethylbenzene	1.0	0.050	1.000	0	103	80	120					
Xylenes, Total	3.1	0.10	3.000	0	104	80	120					
Surr: 4-Bromofluorobenzene	1.2		1.000		123	66.6	132					
Sample ID RB	SampT	ype: ME	BLK	Tes	tCode: El							
Client ID: PBS	Batch	Batch ID: B43104			RunNo: 4							
Prep Date:	Analysis D	Analysis Date: 5/26/2017			SeqNo: 1356874 Units:				ts: mg/Kg			
Analyte	Result	PQL	SPK value	SPK Ref Val	%REC	LowLimit	HighLimit	%RPD	RPDLimit	Qual		
Benzene	ND	0.025										
Toluene	ND	0.050										
Ethylbenzene	ND	0.050										
Xylenes, Total	ND	0.10										
Surr: 4-Bromofluorobenzene	1.2		1.000		117	66.6	132					

Qualifiers:

- Value exceeds Maximum Contaminant Level.
- D Sample Diluted Due to Matrix
- H Holding times for preparation or analysis exceeded
- ND Not Detected at the Reporting Limit
- R RPD outside accepted recovery limits
- S % Recovery outside of range due to dilution or matrix
- В Analyte detected in the associated Method Blank
- E Value above quantitation range
- J Analyte detected below quantitation limits
 - Sample pH Not In Range
- RL Reporting Detection Limit

P

Sample container temperature is out of limit as specified

Page 6 of 6



