RECEIVED

Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR

FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018

BUREAU OF LAND MANAGEMENT				5. Lease Serial No. NOG13121809	
Do not use th	ilis formi for proposais	ORTS ON WELLS Mana to driff or to re-enter an APD) for such proposals		6. If Indian, Allottee	or Tribe Name
SUBMIT IN TRIPLICATE - Other instructions on page 2			7. If Unit of CA/Agreement, Name and/or No. NMNM135217A		
1. Type of Well ☐ Gas Well ☐ Other ☐ Other				8. Well Name and No. N ESCAVADA UNIT #328H	
2. Name of Operator WPX Energy Production, LLC				9. API Well No. 30-043-21286	
3a. Address	NM 87410	3b. Phone No. (include area code 505-333-1816	2)	10. Field and Pool or Exploratory Area ESCAVADA N,MANCOS	
4. Location of Well (Footage, Sec. SHL: 1918' FSL & 1267' FEL SE BHL: 1156' FNL & 2291' FWL S			11. Country or Parish Sandoval, NM	ı, State	
12.	CHECK THE APPROPRIATE B	OX(ES) TO INDICATE NATURE	OF NOTI	CE, REPORT OR OT	HER DATA
TYPE OF SUBMISSION		TYPE OF ACTION			
□Notice of Intent	Acidize	Deepen	Prod	luction (Start/Resume)	☐ Water ShutOff
	☐ Alter Casing	☐ Hydraulic Fracturing		amation	☐ Well Integrity
Subsequent Report	☐ Casing Repair	☐ New Construction		omplete	Other Final
Final Abandonment Notice	☐ Change Plans ☐ Convert to Injection	☐ Plug and Abandon ☐ Plug Back		nporarily Abandon er Disposal	OIL CONS. DIV DIST. 3
OK					AUG 1 0 2017
the proposal is to deepen direct the Bond under which the wor	tionally or recomplete horizontally k will be perfonned or provide the	y, give subsurface locations and me e Bond No. on file with BLM/BIA	easured and . Required	d true vertical depths of subsequent reports m	rk and approximate duration thereof. If of all pertinent markers and zones. Attach ust be filed within 30 days following 3160-4 must be filed once testing has been

Psi Test W/ Antelope Services: Shell Test High 2,000 Psi for 30 Min: Well Head Connection, 7" intermediate Casing, Blind Rams, Kill Valves, Relief side Valves, Stinger flex hose, All outer Valves in Choke Manifold,7" Casing String Low 250 psi for 5 Min: Well Head Connection, 7" intermediate Casing, Blind Rams, Kill Valves, Hellef side Valves, String Low 250 psi for 5 Min: Well Head Connection, 7" intermediate Casing, Blind Rams, Kill Valves, Hellef side Valves, String Low 250 psi for 5 Min: Well Head Connection, 7" intermediate Casing, Blind Rams, Kill Valves, Hellef side Valves, String Low 250 psi for 5 Min: Well Head Connection, 7" intermediate Casing, Blind Rams, Kill Valves, Hellef side Valves, String Low 250 psi for 5 Min: Well Head Connection, 7" intermediate Casing, Blind Rams, Kill Valves, Hellef side Valves, String Low 250 psi for 5 Min: Well Head Connection, 7" intermediate Casing, Blind Rams, Kill Valves, String Low 250 psi for 5 Min: Well Head Connection, 7" intermediate Casing, Blind Rams, Kill Valves, String Low 250 psi for 5 Min: Well Head Connection, 7" intermediate Casing, Blind Rams, Kill Valves, String Low 250 psi for 5 Min: Well Head Connection, 7" intermediate Casing, Blind Rams, Kill Valves, String Low 250 psi for 5 Min: Well Head Connection, 7" intermediate Casing, 80 psi for 5 Min: Well Head Connection, 7" intermediate Casing, 80 psi for 5 Min: Well Head Connection, 7" intermediate Casing, 80 psi for 5 Min: Well Head Connection, 7" intermediate Casing, 80 psi for 5 Min: Well Head Connection, 80 psi f All outer Valves in Choke Manifold, all tested good and recorded on chart

7/20/17- Drilling ahead 6-1/8" lateral.

7/21/17, TD 6-1/8" lateral @ 11004' (TVD 5074')

Ran Production Casing Liner, 120 jts & 2 Pup jts of 4.5", 11.6# P-110, LT&C. CSG set @ 10999', LC @ 10950', TOL @ 5640', RSI @ 10928'.

"Cement 4.5""Casing Liner with 35% excess figured (Halliburton Services) 5,000 Psi Test on LinesFlush Water @ 8.3# (10 BBLS), followed by Tuned Spacer @ 11.5# (40 BBLS), followed by Primary Cement @ 13.3# { 122 Bbls/505 sks ExtendaCem * } followed by Displacement Totaling 126 Bbls { 40 Bbls MMCR & 40 Bbls of 2% KCL, 10Bbld fresh, 37Bbls of 2% KCL | Land Plug 1500 PSI & Bump up to 2450 PSI & Hold 5 min Floats Held got 1.0 Bbl Back on Bleed off Plug Down 7/21/2017 22:45hrs" "Set ZXP Pack off w/ 50 K, Pull up off and Quick Psi Test of Packer Seals with Pump Truck, Good Test, Sting out of Liner Hanger, W/ Pump truck Circ Out 20 Bbl Good Cement to Surface"

7/22/17- Run Tie Back Frac String, 125 jts & 3 pups of 4.5", 11.6# P-110, LT&C 0'GL to 5,640' MD TOL. Pressure tested tie back @ 2,000psi for 30 min- good test RD

W

ill report 4-1/2" test on completion paper work.					
14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)					
Lacey Granillo	tle Permit Tech III				
Signature	eate 7/24/17				
THE SPACE FOR FEDERAL OR STATE OFICE USE					
Approved by					
	Title	Date			
Conditions of approval, if any, are attached. Approval of this notice does not warrant of certify that the applicant holds legal or equitable title to those rights in the subject leas which would entitle the applicant to conduct operations thereon.	Office				

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.