

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB No. 1004-0137
Expires: July 31, 2010

SUNDRY NOTICES AND REPORTS ON WELLS
*Do not use this form for proposals to drill or to re-enter an
abandoned well. Use Form 3160-3 (APD) for such proposals.*

SUBMIT IN TRIPLICATE - Other instructions on page 2.

1. Type of Well

☐ Oil Well

☒ Gas Well

☐ Other

2. Name of Operator

Hilcorp Energy Company

3a. Address

PO Box 4700, Farmington, NM 87499

3b. Phone No. (include area code)

505-599-3400

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Surface UNIT L (NWSW), 1850' FSL & 1190' FWL, Sec. 17, T30N, R6W

5. Lease Serial No.

NM-03385

6. If Indian, Allottee or Tribe Name

7. If Unit of CA/Agreement, Name and/or No.

San Juan 30-6 Unit

8. Well Name and No.

San Juan 30-6 Unit 80

9. API Well No.

30-039-07843

10. Field and Pool or Exploratory Area

Blanco MV

11. Country or Parish, State

Rio Arriba, New Mexico

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☐ Subsequent Report

☒ Final Abandonment Notice

TYPE OF ACTION

☐ Acidize

☐ Alter Casing

☐ Casing Repair

☐ Change Plans

☐ Convert to Injection

☐ Deepen

☐ Fracture Treat

☐ New Construction

☐ Plug and Abandon

☐ Plug Back

☐ Production (Start/Resume)

☐ Reclamation

☐ Recomplete

☐ Temporarily Abandon

☐ Water Disposal

☐ Water Shut-Off

☐ Well Integrity

☒ Other **FAN**

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof.

If the proposal is to deepen directionally or recompleat horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompleat in a new interval, a Form 3160-4 must be filed once Testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.)

The subject well was P&A'd on 9/9/05. Reclamation was completed and the location is now ready for final closure approval. The location was inspected and passed on 8/15/17 with Bob Switzer. Please remove this well from the Hilcorp Energy Company bond.

OIL CONS. DIV DIST. 3

SEP 1 2017

RECEIVED

AUG 24 2017

**Farmington Field Office
Bureau of Land Management**

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)

Christine Brock

Title **Operations/Regulatory Technician**

Signature

Christine Brock

Date

8/23/17

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved by

Sup NRS

Title

Sup NRS

Date

8/25/17

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office

FRO

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

RCC Reclamation Completion				Location Name: <u>ST 30-6 UNIT 80</u> Date: <u>8-15-2017</u> Revision 3 (3/21/17)								
API#: <u>3003907843</u>				UL-Sec-Twn-Rng: <u>Sec 17 T30N-R6W</u> Lat/Long: <u>36.81036 -107.49062</u>								
Surface Owner: <u>BLR</u>				Lease#: <u>NM-03385</u> County/State: <u>RIO ARIZONA NM</u>								
Pipeline Owner:				Twin/Co-Locate Well Name & Operator:								
Onsite: <u>Sam Isaver</u>		Agency Inspector: <u>Bobb Swetm</u>		Contractor:								
Seed Mix:												
Interim Reclamation		Completed	Incomplete	N/A	Final Reclamation	Completed	Incomplete	N/A	Remediation	Completed	Incomplete	N/A
Have pit sample results been approved					3rd party pipeline removed		✓		Facilities stripped			
Has water been removed from pit					Anchors removed		✓		Certificate of waste issued & approved			
Have pit marker photos been taken					Equipment and piping removed		✓		Depth:			
Has certificate of waste been issued & approved					Power poles removed		✓		Width:			
Have all pit contents been removed					Cathodic protection removed		✓		Length:			
Has sample after content removal been taken					Vegetative cages removed		✓		Date of Excavation Start:			
Is location contoured					CMP's removed		✓		Date of Excavation End:			
Is there 4' of cover over pit					Non native gravel buried or removed		✓		Date of Backfill Start:			
Has top soil been spread evenly					Noxious weeds removed or sprayed		✓	✓	Date of Backfill End:			
Has all non-native gravel been buried or removed					Invasive weeds removed or sprayed			✓	Yards Hauled Out:			
Has pit liner been removed					Contouring complete		✓		Impacted Soil Hauled To:			
Has all trash been removed					Top soil spread		✓		Yards Hauled In:			
Have all weeds been removed					Diversion clean and functional		✓		Fresh Soil Hauled in From:			
Teardrop allows vehicle access to all facilities					Silt trap clean and functional		✓		Approval to backfill			
Drainage ditches allow adequate run off					Cattle guard / gates removed			✓	Back fill mechanically compacted			
All non-traffic areas disked properly					Cellar / mouse hole covered		✓		Facilities reset			
All non-traffic areas seeded					Erosion under control		✓		Trash and debris removed			
Seeded areas have been mulched					Location properly ripped		✓	✓	Close Out Completed			
Noxious weeds have been removed or sprayed					Location properly disked		✓		Soil Removal Sundry Ready to be Filed			
Invasive weeds have been removed or sprayed					Location seeded		✓					
Barriers set to deter traffic					Photo transect installed			✓				
Silt traps are functional					Access road properly closed		✓					
Culverts are functional					Public use controlled		✓					
Upper diversion is functional					Barriers in place		✓	✓				
Erosion under control					Grazing controlled		✓					
Photo transect installed					P&A marker installed & legible		✓					
Have wellhead cages and Jersey barriers been removed					Well sign removed		✓					
Have reclamation pictures been taken					Growth at least 70%		✓					
Growth at least 70%					Trash and debris removed from location		✓					
Agency Inspection Date:					Final reclamation photos taken		✓					
Sundry is ready to file					Agency Inspection Date: <u>8-15-2017</u>		✓					
Comments:					FAN Ready to be filed		✓		Comments:			
					Ready TO FILE FAN							