



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/10/17 Operator: Enervest Operating, LLC API # 30-039-22347

Property Name: Jic. Cont. 155 Well No. 13M Location: Unit: L Section: 30 Township: 26N Range: 5W

Well Status(Shut-In or Producing) Initial PSI: Tubing Intermediate Casing 82 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	0		82		
10 min	0		82		
15 min	0		82		
20 min	0		80		
25 min	0		80		
30 min	0		80		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u> </u>	<u> </u>
Surges <u> </u>	<u> </u>
Down to Nothing <u> </u>	<u> </u>
Nothing <u>✓</u>	<u> </u>
Gas <u> </u>	<u> </u>
Gas & Water <u> </u>	<u> </u>
Water <u> </u>	<u> </u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS: blow down to nothing, well was flowing

By Richard Cury

Witness

Operator II
(Position)

E-mail address rcury@enervest.net

OIL CONS. DIV DIST. 3
SEP 05 2017