



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

## BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 8/10/17 Operator: Enervest Operating, LLC API # 30-039-22487

Property Name: Jic. Cont. 155 Well No. 25 Location: Unit: O Section: 30 Township: 26N Range: 5W

Well Status(Shut-In or Producing) Initial PSI: Tubing        Intermediate        Casing 82 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		82		
10 min	0		82		
15 min	0		82		
20 min	0		82		
25 min	0		80		
30 min	0		80		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>      </u>	<u>      </u>
Surges <u>      </u>	<u>      </u>
Down to Nothing <u>      </u>	<u>      </u>
Nothing <u>✓</u>	<u>      </u>
Gas <u>      </u>	<u>      </u>
Gas & Water <u>      </u>	<u>      </u>
Water <u>      </u>	<u>      </u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR        FRESH        SALTY        SULFUR        BLACK       

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE       

REMARKS: No blow, well flowing.

By Rodale Cury

Witness       

Operator II  
(Position)

E-mail address rcury@enervest.net

OIL CONS. DIV DIST. 3  
SEP 05 2017