

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

SEP 05 2017

## **BRADENHEAD TEST REPORT**

(submit 1 copy to above address)

Date of Test 9/8/17 Operator: Enervest Operating, LLC API #30-039-31215					
Property Nan	ne: Jic. Cont. 15	5Well No <u>. 20N</u>	_Location: Uni	t: M_Section: 2	9_Township:_26N_Range: 5W
Well Status(S	Shut-In or Produc	cing) Initial PSI: T	ubing Inte	rmediate C	asing 125 Bradenhead 0
OPEN BRA	ADENHEAD AND	) INTERMEDIATE	TO ATMOSPHI	ERE INDIVIDUAI	LLY FOR 15 MINUTES EACH
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg			FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE		
TIME 5 min O	125		Steady Flow_		
10 min O	125		Surges		
15 min 0	125		Down to Not	hing	
20 min 6	125		Nothing\		
25 min O	125		Gas		-
30 min 0	125		Gas & Water		
			Water		/
If bradenhead flowed water, check all of the descriptions that apply below:					
CLEAR FRESH SALTY SULFUR BLACK					
5 MINUTE SHUT-IN PRESSURE BRADENHEAD O INTERMEDIATE					
REMARKS: Flaving casing didn't drap, thow's for either when plunger come					
up. No blav					
By Rockle	Culy		Witness		
By Robb Culy Witness					
E-mail address reurley & enervestinet					OIL CONS. DIV DIST. 5
					CLD ME 71117