

## NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

## BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 9-1-17 Operator: Enervest Operating, LLC API #30-045-33983	
Property Name_Rio Bravo 27_Well No. 12 Location: Unit L Section 27 Township 31N Range 13W	
Well Status(Shut-In or Producing) Initial PSI: Tubing 10 Intermediate 14 Casing 50 Bradenhead 0	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 5 min 0 50 Int Csg	Steady Flow
10 min	Surges
15 min 0 50	Down to Nothing
20 min 0 50	Nothing
25 min 80	Gas
30 min 50	Gas & Water
	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY	_ SULFUR BLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE M/4	
REMARKS:	
By Ry la v	VitnessOIL CONS. DIV DIST. 3
Luse Operation	ONS. DIV DIV
(Position)	OIL CO. SEP 28 LO
E-mail address	SE