

State of New Mexico  
Energy, Minerals and Natural Resources Department

---

**Susana Martinez**  
Governor

**Ken McQueen**  
Cabinet Secretary

**Matthias Sayer**  
Deputy Cabinet Secretary

**David R. Catanach, Division Director**  
Oil Conservation Division



October 5, 2017

Breck Operating Corp  
Attn: Frances Flournoy  
PO Box 911  
Breckenridge, TX 76424-0911

**Re:** Bradenhead Test  
**Well:** Marshall B #1, UL U Sec 14 Twn 27N Rge 9W, API # 30-045-06483

Ms. Flournoy:

The 2017 Bradenhead test gas analysis on the above well indicates a possible failure. In order to comply with Rule 19.15.16.11, prevent waste and protect fresh water, you are hereby directed to initiate remedial activity before **December 29, 2017**. Initial Surface Casing psi was 15. Initial Production Casing psi was 72. During the 25-minute test the pressure did not blow down past 3 psi.

The Gas analysis and wellbore schematic have been received. Gas analysis show same gas on bradenhead and production casing and tubing.

Reference: **RBDMS MPK1709554717** on future correspondence for this issue.

**Notify the Aztec OCD 24 hours before work is initiated.**

If you have any questions, please call me at 505-334-6178, ext. 116.

Sincerely yours,

Brandon Powell  
Deputy Oil and Gas Inspector  
District III - Aztec

CC: Well File