Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

FORM APPROVED OMB NO. 1004-0137 Expires: January 31, 2018

5. Lease Serial No. NMNM0498

6.	If Indian,	Allottee	or Tribe	Name	
----	------------	----------	----------	------	--

abandoned we		6. If Indian, Allottee or Tribe Name						
SUBMIT IN	7. If Unit or CA/Agreement, Name and/or No.							
Type of Well Oil Well		8. Well Name and No. SCHUMACHER 2F						
2. Name of Operator XTO ENERGY INC	Contact: RHON E-Mail: rhonda_smith@xto			9. API Well No. 30-045-33176-00-S1				
3a. Address	3b. P	hone No. (include area code)	(include area code) 10. Field and Pool or Exploratory Area					
ENGLEWOOD, CO 80112	Ph:	505-333-3215	3-3215 BASIN DAKO BASIN MANC					
4. Location of Well (Footage, Sec., T	., R., M., or Survey Description)			11. County or Parish, St	tate			
Sec 8 T30N R12W NWSW 17	80FSL 670FWL			SAN JUAN COU	NTY, NM			
12. CHECK THE A	PPROPRIATE BOX(ES) TO IN	DICATE NATURE OF	F NOTICE, I	REPORT, OR OTHI	ER DATA			
TYPE OF SUBMISSION	TYPE OF SUBMISSION TYPE OF ACTION							
Notice of Intent	☐ Acidize	□ Deepen	☐ Production	on (Start/Resume)	■ Water Shut-Off			
	☐ Alter Casing	☐ Hydraulic Fracturing	☐ Reclama	tion	■ Well Integrity			
☐ Subsequent Report	☐ Casing Repair	■ New Construction	☐ Recompl	ete	☑ Other			
☐ Final Abandonment Notice	☐ Change Plans	□ Plug and Abandon	□ Tempora	rily Abandon	ShutIn Notice			
	☐ Convert to Injection	☐ Plug Back	☐ Water Di	sposal				
testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection. Per BLM requirements, XTO Energy Inc. is requesting to leave this well shut-in for longer than 90 days due to economic reasons. This well last produced in May 2017 (12 month production data is attached). No surface or subsurface equipment has been nor will be removed during this shut-in period. The well will be re-evaluated yearly based on economic and operational considerations. XTO Energy has a long term shut-in compliance agreement with the NMOCD (ACOI No. 2017-002) dated 08/02/2017. OIL CONS. DIV DIST. 3 AUG 24 2017								
Stapproved until 9/1/2018								
14. I hereby certify that the foregoing is true and correct. Electronic Submission #385323 verified by the BLM Well Information System For XTO ENERGY INC, sent to the Farmington Committed to AFMSS for processing by WILLIAM TAMBEKOU on 08/21/2017 (17WMT0607SE)								
Name (Printed/Typed) RHONDA	SMITH	Title REGULA	ATORY CLE	RK				
					× *			
Signature (Electronic S	Submission)	Date 08/18/20	017					
,	THIS SPACE FOR FE	DERAL OR STATE (OFFICE US	E				
Approved By WILLIAM TAMBEKO	TitlePETROLEI	UM ENGINE	ER	Date 08/21/2017				
Conditions of approval, if any, are attache certify that the applicant holds legal or equ which would entitle the applicant to condu	uitable title to those rights in the subject		ton					
Title 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s			willfully to mal	te to any department or ag	gency of the United			

(Instructions on page 2) ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED **





