

# NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

#### **BRADENHEAD TEST REPORT**

OCT 31 2017

OIL CONS. DIV DIST. 3

(submit 1 copy to above address)

Date of Test 10/3/2017 Operator Western Minerals & Oil API # 39-82334

Property Name\_Hurt\_Well No. 1 Location: Unit\_E Section\_11 Township\_25N Range\_3W

Well Status(Shut-In or Producing) Initial PSI: Tubing 38 Intermediate -- Casing 42 Bradenhead 12.0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

			PRESSU	RE		FLOW CHARACTERISTICS					
Testing		Bradenl	head	INTER	RM	BRADENHEAD INTERMEDIATE					
	BH	Int	Csg	Int	Csg						
TIME	1.2		12.0								
5 min_	1.2		42.0			Steady Flow					
10 min_	_1.2_		42.0			Surges					
15 min_	_1.4_		42.0			Down to Nothing X					
20 min_	_2.2_		42.0			Nothing X					
25 min_	_2.5_		42.0			Gas					
30 min_	_2.6_		42.0			Gas & Water					
						Water					
If bradenhead flowed water, check all of the descriptions that apply below:											
	CLEAI	R	FRESH_	5	SALTY	BLACK					
5 MINUTE SHUT-IN PRESSURE BRADENHEAD 1.3 INTERMEDIATE											
REMARKS:											
The well blew down to nothing within 6 minutes with no liquids											
By Bob Chenault Witness_Steven Gallegos											
Pumper (Position)											
E-mail addressBob@ccinm.com											



# NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD AZTEC NM 87410 (505) 334-6178 FAX: (505) 334-6170 http://emnrd.state.nm.us/ocd/District III/3distric.htm

### OIL CONS. DIV DIST. 3

#### **BRADENHEAD TEST REPORT**

OCT 3 1 2017

(submit 1 copy to above address)

Date of Test 10-3-2017 Operator Western Minerals & Oil API #

Property Name\_Jillison\_Well No. 1 Location: Unit\_Section 1 Township 25N Range 2W

Well Status(Shut-In or Producing) Initial PSI: Tubing 81 Intermediate -- Casing 221 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

			PRESSU	RE		FLOW CHARACTERISTICS						
Testing		Braden	head	INTE	RM		BRADENHEAD	INTERMEDIATE				
U	BH	Int	Csg	Int	Csg							
TIME						-						
5 min	0		221			Steady Flow						
						-						
10 min	0		221			Surges						
_						0						
15 min	0		221			Down to Not	hing					
						20111101101	B					
20 min	0		221			Nothing						
20 1111												
25 min	0		221			Gas						
25 11111_						043						
30 min	0		221			Gas & Water		· · · · · · · · · · · · · · · · · · ·				
50 mm_						Oas & Water						
						Water						
Water												
Ifbud	nhood	flowed	unton oho	als all of th	a decomintion	a that apply hal						
II brade	innead	nowed w	vater, che	ck all of th	le description	s that apply belo	<u>ow:</u>					
CLEAR FRESH SALTY SULFUR BLACK												
C MATNIN			DECOUD			D 0						
5 MINU	TE SH	UI-IN F	RESSUR	E.	BRADENHEA	AD_0	INTERMEDIAT	E				
REMAR	KS:											
				No P	ressure							
By Bob Chenault Witness Steven Gallegos												
Pumper												
(Position)												
E-mail a	ddress	Bob@c	cinm.com									