RECEIVED

Form 3160-5 (June 2015)

UNITED STATES DEPARTMENT OF THE INTERIOR 14 2817

FORM APPROVED OMB No. 1004-0137 Expires: January 31, 2018

BUREAU OF LAND MANAGEMENT					5. Lease Serial No.		
SUNDRY NOTICES AND REPORTS ON WELLS Field Office					N00C1420559		
Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.					6. If Indian, Allottee	or Tribe Name	
					7. If Unit of CA/Agreement, Name and/or No.		
SUBMIT IN TRIPLICATE - Other instructions on page 2 1. Type of Well					NMNM135217A		
⊠Oil Well ☐Gas Well ☐Other					8. Well Name and No. 7.0.1 N ESCAVADA UNIT #315H		
2. Name of Operator WPX Energy Production, LLC				g (60111	9. API Well No. 30-043-21888		
3a. Address	(include area code		10. Field and Pool or Exploratory Area ESCAVADA N,MANCOS				
PO Box 640 Aztec, NM 87410 505-333-18							
4. Location of Well (Footage, Sec., T.,R.,M., or Survey Description) SHL: 1583' FSL & 250' FWL, Sec 10, T22N, R7W BHL: 2306' FSL & 536' FWL, Sec 4 T22N, R7W					11. Country or Parish, State Sandoval, NM		
12	2. CHECK THE APPROPRIATE BOX	(ES) TO IND	DICATE NATURE	OF NOTIC	E, REPORT OR OT	HER DATA	
TYPE OF SUBMISSION			TYPE OF ACTION				
□Notice of Intent □Acidize		Deepen		Produ	ction (Start/Resume)	☐ Water ShutOff	
	☐Alter Casing	Hydrauli	c Fracturing Recl		mation	☐ Well Integrity	
Subsequent Report	☐ Casing Repair	☐ Casing Repair ☐ New Co		ruction		Other Final	
☐Final Abandonment Notice	☐ Change Plans ☐ Plug ar		d Abandon	Abandon		Casing	
T mai Abandonment Nouce	☐Convert to Injection ☐Plug Bac		k	☐ Water Disposal			
is ready for final inspection.) 1/3/17- MIRU- "Psi Test 7", Test I 1/4/17-Drilling ahead 6-1/8" later 1/5/17-Ran 175 Jts & 3 pup jts of the street on Lines Flutation of Lines Flutation of Lines Flutation of Lines Held fruck, Good Test, Sting out of Lines 1/6/17-Run Tie Back Frac String,	digh 1500 Psi for 30 Min- good test ral. TD 6-1/8" lateral @ 13308' (TVD 5 4.5" 11.6#, P-110, LT&C, CSG set @ 1 sh Water @ 8.3# {10 BBLS }, followed by Displacement Totaling 178 got 1.5 Bbl Back on Bleed off Plug Do Hanger, W/ Pump truck Circ Out 45 l 125 jts & 4 pups of 4.5", 11.6# P-110 od test recorded on Antelope Service	3304', LC @ 3.7 Bbls { 40 Ewn 11/05/20 Bbl Good Cer 0, LT&C 0'GL	13258', RSI @ 132 Spacer @ 11.5# {4 Bbls MMCR,70 Bbl 117 22:30 Set ZXP ment to Surface to 5,474' MD TOL	236'_TOL @ 5 40 BBLS }, fo s of 2% KCL, Pack off w/	5474'. Blowed by Primary C & 20 fresh, 48.6 bb 50 K, Pull up off and Mandrel 35k & 30k	the operator has detennined that the site over 2 1 2017 The state of Packer Seals with Pump on Seal assembly. Pressure Test Tie Back OIL CONS. DIV DIST. 3	
14. I hereby certify that the forego	ing is true and correct. Name (Printed	(Typed)					
Lacey Granillo			Title Permit Tech III			NOV 2 7 2017	
Signature			Date 11/14/17				
	THE SPACE F	OR FEDE	RAL OR ST	ATE OF	CE USE	× /	
Approved by							
			Title			Date	
Conditions of approval, if any, are certify that the applicant holds leg which would entitle the applicant t	attached. Approval of this notice does all or equitable title to those rights in to conduct operations thereon.	s not warrant the subject lea	or Office				
Title 19 II S C Section 1001 and T	itle 42 II S C Section 1212 make it a	orime for cov	namon Imoveinals	and willed	lu to males to anu do	northwant or account of the Linited States	