2	Form 3160-5 (August 2007) UNITED STATE SECEIVED DEPARTMENT OF THE INTERIOR BUREAU OF LAND MANAGEMENT				FORM APPROVED OMB No. 1004-0137 Expires: July 31, 2010 5. Lease Serial No.			
	Do not us		EPORTS ON WELLS		NM-02294 6. If Indian, Allottee or Tribe Name			
		well. Use Form 3160-3 (A		ls.				
		UBMIT IN TRIPLICATE - Other inst	tructions on page 2.		7. If Unit of CA/Agreement, Na	me and/or No.		
	1. Type of Well Oil Well Image: Constraint of the second				8. Well Name and No. Whitley 10			
	2. Name of Operator		9. API Well No.					
	Hilcorp Energy Company 3a. Address 3b. Phone No. (include area code)				30-045-20720 10. Field and Pool or Exploratory Area			
	PO Box 4700, Farmingt	505-599-3400	uc)	Basin Fruitland Coal				
	4. Location of Well <i>(Footage, Sec., T.,F.</i> Surface Unit E (SV	R.,M., or Survey Description) VNW), 1850' FNL & 850' FV	VL, Sec . 17, T27N, R0	9W	11. Country or Parish, State San Juan , New Mexico			
	12. CHECK	THE APPROPRIATE BOX(ES)	TO INDICATE NATURE	OF NO	TICE, REPORT OR OTHE	R DATA		
	TYPE OF SUBMISSION		TYPE	OF AC	TION			
ſ	Notice of Intent	Acidize	Deepen	F	Production (Start/Resume)	Water Shut-Off		
1		Alter Casing	Fracture Treat	F	Reclamation	Well Integrity		
2	Subsequent Report	Casing Repair	New Construction		Recomplete	X Other		
1	X Final Abandonment Notice	Change Plans Convert to Injection	Plug and Abandon Plug Back		Femporarily Abandon Water Disposal	FAN		
	Testing has been completed. Final determined that the site is ready for The subject well was P &	&A'd on 9/11/2012. Reclam was inspected and passed	nly after all requirements, includ	and th	amation, have been completed and he location is now reac vitzer. Please remove t	l the operator has		
			DEC	05	2017			
	14. I hereby certify that the foregoing is	true and correct. Name (Printed Types	d)					
	Christine Brock		Title Operat	ions/R	egulatory Technician			
Signature limistice Brock Date 11/14/2017								
THIS SPACE FOR FEDERAL OR STATE OFFICE USE								
Approved by Title Title								
	(Instruction on page 2)		NMOO	V				
			NMOC	U				

Have pit sample results been approved Sid party pipeline removed Faccilize subject Haw pit marker been removed from pit Anchore removed Certificate of waste basen favored Certificate of waste basen issued & approved Haw pit marker photas been inserved Equipment and piping removed Width: Length: Has cellulate of waste basen inserved Cortificate of waste basen inserved Width: Length: Has setting effer content basen removed Cortificate of waste basen inserved Width: Length: Is location contoured Cortificate of waste basen inserved Date of Boarwalion Start: Date of Boarwalion Start: Is location contoured Is location contoured Cortificate of over over pit Date of Boarwalion Start: Date of Boarwalion Start: Has attion contoured Is location contoured Cortificate or removed Date of Boarwalion Start: Date of Boarwalion Start: Has attion contoured growpred eventy Is location contoured growpred Variation Start: Date of Boarwalion Start: Has attion contoured growpred Cortificate or removed Is location contoured or properved Variation Contoured or properved Has attinacon teamored or properved Cortificate or contour	- حت				·		
Surface Owner: BLM Leasest M.M. D.2.2.94 Country/State: S.M.M. Plpeline Owner: Twin/Co-Locate Well Name & Operator: Contractor: Seed Mbx Onlia: Sum J.A.O.C. Aprice Jungeoint Country/State: S.M.M. Intervini Reclamation Image: Seed Mbx Seed Mbx Recreptore Seed Mbx Intervini Reclamation Image: Seed Mbx Recreptore Seed Mbx Recreptore Use of the articles of watch been stem. Image: Seed Mbx Recreptore	n 3 (3/21/17)	Date: 11-9-2017 Revision				on	
Pipeline Owner: TwinCo-Locate Well Name & Operator: Onsize: Agency Impediation Send Mixe Titterim Reclamation Impediation Remediation Titterim Reclamation Impediation Remediation Titterim Reclamation Impediation Remediation Titterim Reclamation Impediation Remediation Titterim Reclamation Impediation Impediation Titterim Reclamation Impediation Remediation Titterim Reclamation Impediation Removed	593	Lat/Long: 36.5768.2 -107.816	17	al	UL-Sec-TWN-Rng: E TZTAL R94/ Se		#: 30-045-20720
Onstate: Agency Lapestor: March Contractor: Seed Mbb: Intertimi Reclamation Image: Contractor: Image: Contractor: Seed Mbb: Remediation Image: Contractor: Seed Mbb: Have pit except example results bean supported Image: Contractor: Seed Mbb: Remediation Image: Contractor: Remediation: Image: Contractor: Remediation Image: Contractor: Remediation: Image: Contract		County/State: 57 HM			Lease# NM 02294		rface Owner: BLm
Oralitic Agency Impedant Mark Mark Mark Contractor: Seet Mate Intercion: Reclamation Image: Section of the sectin of the section of the section of the section of the	ļ				Twin/Co-Locate Well Name & Operator:		eline Owner:
Interim Reclamation Print Reclamation Print Reclamation Print Reclamation Remediation Have all stample reads been superved Image of the stample reads been superve		Seed Mix:				Agency Inspe	
Interpretation Interpr				_	1200 - ONDAN		-Mm Arduez
Take pit sample results bean approved Image: Status Facilities and special same of waste insured & approved Cettificate of waste insured & approved Cetificate of waste insured & approved </td <td>Completed Incomplete NIA</td> <td>Remediation</td> <td>NIA</td> <td>Completed</td> <td></td> <td>Completed Incomplete N/A</td> <td>Interim Reclamation</td>	Completed Incomplete NIA	Remediation	NIA	Completed		Completed Incomplete N/A	Interim Reclamation
Has welt hen removed form jbl. Anchom removed Cettification of waste based & approved Have pit marker photos been taken Equipment and piping removed Width: Have and take of waste basen taken Cathodo protection removed Width: Have and juing removed Cathodo protection removed Used Have and juing removed Cathodo protection removed Date of Excavation Start: Is location contoured Is location contoured Date of Excavation Start: Is location contoured Notobus weeds removed Date of Excavation Start: Has and locating removed Inscattor over pit Date of Backfill Start: Has and non-networe gravel Inscattor encoved Date of Backfill Start: Has and non-networe gravel Inscattor encoved Part Haused Out Has and item bean removed Top ool grand Part Haused Out Has all inch-tattle sens removed Stit trap clean and functional Pare All stated on the start Has all non-tattle areas allowed property Cateling purpties removed Pare All stated on the start Has all non-tattle areas allowed property Cateling purpties removed Pare All stated for the start All non-tattle areas allowed properif Cateling purptify removed <td></td> <td>Facilities stripped</td> <td>-+-1</td> <td>_</td> <td>Srd party pipeline removed</td> <td></td> <td>/e olt samola results baan approved</td>		Facilities stripped	-+-1	_	Srd party pipeline removed		/e olt samola results baan approved
Have git marker photes been taken Equ(pment and piping removed Deptr: Has certificate (varies been issued & approved Power poles removed Largh: Has certificate (varies been issued & approved Power poles removed Date of Excavation Start: Has and their content removal been taken Cothodic protection removed Date of Excavation Start: Is brazition control Cothodic protection removed Date of Excavation Start: Is there 4 of cover over pit Non native gravel buried or removed Date of StackWill Start: Has top approxement memored Insection weeds removed or sprayed Part StackWill Start: Has pit lambe been removed Top col sprand Prote StackWill Start: Has and weeds been removed Top col sprand Prote StackWill Start: Has pit lambe been removed Top col sprand Prote StackWill Start: Has pit lambe been removed Top col sprand Prote StackWill Start: Has all trach been removed Corticuting comparison Prote StackWill Start: Has all non-refers aread stack poperly Celle gurand functional Prote StackWill Start: Has all non-refers aread stack poperly Celle gurand functional Prote StackStal	╺╍╂╍╌╂╍╍┦			5			
Has certificate of waste been issued & approved Power projee removed Langth: Has senite abeen removed Gethodic protection removed Date of Excervation Start: Has senite after content COLP at manoved Date of Excervation Start: Is location contoured ColP at manoved Date of Excervation Start: Is location contoured CoLP at manoved Date of Excervation Start: Has senite and workly gravel baseh turied or removed Notous weeds removed or removed Date of Excervation Start: Has senite and workly gravel baseh turied or removed Notous weeds removed or removed Variet Haude Out: Has all insenitives gravel baseh turied or removed Contouring complete Variet Haude Out: Has all fice been removed Contouring complete Variet Haude Out: Has all insenite been removed Silt rap clean and functional Fresh. Sold Haude In: Pariet Baltwide property Coller / mouse hole covered Parist Haude Out: All non-turific areas allow doc prayed Coller / mouse hole covered Parist Haude Out: Nadous weeds have been removed or approved Location property disked Parist Haude Out: Nadous weeds have been removed or approved Location property disked Coller / mouse hole covered	╺╌╂╼╍╂╾╼╂═╼┙		-+-1	77			
Linke all pit contents been removed Length: Las sample after content removal been taken Catholic protection removed Date of Excavation Start; Las board on control CMP a removed Date of Excavation Start; Las top soft been spread evenly Non native gravel burled or removed Date of Excavation Start; Has top soft been spread evenly Non native gravel burled or removed Date of Excavation Start; Has pit liber been removed Contouring complete Date of Excavation Start; Has pit liber been removed Contouring complete Date of Excavation Start; Has pit liber been removed Contouring complete Date of Excavation Start; Has pit liber been removed Contouring complete Unpacted Scil Hauled To; Has al trab been removed Diversions clean and functional Paptroval to backfill Draining ditches allow adequates run off Cation property Cation property All non-taffic areas eacted Erection under control Trash and dabit removed Seaded areas have been mulched Location property dised Cation property dised Nodus weade have been removed or sprayed Location property dised Cation property dised	╾╂╼╉╍╉╼┙						
Has sample effer content removal been taken Vegetative cages removad Date of Boardelin Start: La location contoured CAIP's removad Date of Boardelin Start: La brack of cover over pit Non salve grave builed or removed Date of Boardelin End: Has to pail been spread evenly Non salve grave base framoved or prayed Date of Boardelin End: Has pail been spread evenly Non salve grave been temoved Date of Boardelin End: Has all tach been removed Contouring complete Impacted Soil Hauled To: Has all tach been removed Contouring complete Impacted Soil Hauled To: Has all tach been removed Contouring complete Yerdet Hauled To: Has all tach been removed Contouring complete Yerdet Hauled To: Has all tach been removed Contouring complete Yerdet Hauled To: Have sall veeds been removed Silt trip class removed Yerdet Hauled To: Prainege diches allow adocutes run off Coalie guard pate removed Prack Soil Hauled To: All nor-kraffic acreas disked properly Coalie guard pate removed Prack Soil Hauled To: Seaded areas have been mulched Location properly tipped Coalie guard pate removed Track Soil Hauled To: Invasiv	╾╁╼╍┧╼┾┯╼┙			1			ويستحدث والمراجع والمراجع والمتحافظ والمستحد والمتحافظ والمتحاف والمحافظ
Is brackin contoured CMP removed Date of Backfill Start Is there 4' of cover over pit Non nailve gravel builed or removed Date of Backfill Start Has top soft been spread evenly Nodous weeds removed or sprayed Date of Backfill Start Has all non-nailve gravel been builed or removed Insrvative weeds removed or sprayed Varies Huiled Oct Has all non-nailve gravel been removed Contouring complete Varies Huiled Oct Has all trash been removed Contouring complete Varies Huiled Tor Has all trash been removed Diversions clean and functional Varies Huiled Tor Frearbox allow exhibtle access to all facilities Sitt trap clean and functional Presh Sitt frap clean Drainage ditches allow edequates run off Califor promoved Back fill mechanically compacted All non-traffic areas aseed Errolin under control Back fill mechanically compacted All non-traffic areas aseed Errolin under control Frash and dabit removed Readed areas have been removed or sprayed Location properly diskd Califor promoved Sitt trap cale and shave been removed or sprayed Location properly diskd Califor transect installed Barriers in traffic out of traneed installed Photo transect installed	─ ┼┈{╶┤ ─┤ ─ ┘						
Is here 4' of cover over pit Non native gravel burled or removed Date of Backfill Start: Has be non-moved Non native gravel burled or removed Date of Backfill Start: Has all non-heref weeds removed Insvestive weeds removed or sprayed Date of Backfill Start: Has all there been removed Insvestive weeds removed Impacted Soil Hauled Out Has all there been removed Top soil spraed Impacted Soil Hauled To: Has all veeds been removed Diversion clean and functional Fresh Soil Hauled In From: Hars all weeds been removed Calling aurd / gates removed Back fill mechanically compacted Onrienge diches allow adequate run off Calling aurd / gates removed Back fill mechanically compacted All non-traffic areas disked properly Calling aurd / gates removed Freah Soil Hauled In From: Nodous weeds have been removed or sprayed Location properly ripped Cleae VIII Competed Nodous weeds have been removed or sprayed Location properly ripped Cleae OUI Competed Nodous weeds have been removed or sprayed Location properly ripped Cleae OUI Competed Nodous weeds have been removed or sprayed Location properly ripped Cleae OUI Competed Nodous weeds have been removed or sprayed Location							
Has top soil been spread evenly Nordous weeds removed or sprayed Dato or Backfill End: Has all non-neilve gravel been burled or removed Contouring complete Impacted Scill Hauled To: Has pit littre been removed Contouring complete Impacted Scill Hauled To: Has pit littre been removed Contouring complete Yards Hauled To: Top soil spread Top soil spread Yards Hauled To: Fastrop Elittres elitives Sit trap clean and functional Approval to backfill Drainage ditches elitive webtles access to ell facilitives Cattle guard / pates removed Approval to backfill All non-traffic areas disked property Cattle guard / pates removed Cattle guard / pates removed Fastlittes reast Nodous weeds have been mulched Location property risped Cattle guard / pates removed Cattle guard / pates removed Nodous weeds have been mulched Location property risped Location property risped Case Out Completed Nodous weeds have been moreoved or sprayed Location property risped Soil Removal Sundry Ready to be Filed Nodous weeds have been mulched Photo transect installed Photo transect installed Soil Removal Sundry Ready to be Filed Griverise re functional Photo transect installed	╾╁╸┼╶┿╸╴	Date of Backfill Start:		. 1			hare 4' of cover over plt
Has all non-netitive gravel bean burled or removed Insvastive weeds removed or sprayed Yards Hauled Out: Has all table bean removed Contouring complete Impacted Soil Hauled To: Has all table bean removed Diversions clean and functional Yards Hauled In: Have all tables access to all facilities Diversions clean and functional Presh Soil Hauled In: Drainage ditthes allow adoptate access to all facilities Diversions clean and functional Presh Soil Hauled In: Drainage ditthes allow adoptate access to all facilities Diversions clean and functional Presh Soil Hauled In: All non-tarfitic areas allowed or prayed Celler / mouse hole covered Pack II mechanically compacted Nodous weeds have been manoved or sprayed Location properly ripped Cleae Out Completed Nodous weeds have been memoved or sprayed Location properly ripped Cleae Out Completed Nodous weeds have been removed or sprayed Location acceded Soil Removal Sundry Ready to be Filed Sit traps are functional Photo transact Installed Photo transact Installed Photo transact Installed Upper diversion is functional Photo transact Installed Leightie Photo transact Installed Leightie Photo transact Installed Leightie Have realination pictures been removed	╾┼╌┾┈┼╼╸		++	₩.X			
Has pit liner been removed Contouring compteta Impacted Soll Hauled To: Has pit liner been removed Top soll spread Yards Hauled In: Have all weaks been removed Diversions clean and functional Fresh Soll Hauled In: Teardrop allows vehicle access to all facilities Silt trap clean and functional Fresh Soll Hauled In: Drainage ditches allow adequate run off Catlie guard (gates removed Back fill mechanically compacted All non-traffic areas asked property Catlie guard (gates removed Eroston under control Back fill mechanically compacted Nadous weads have been removed or sprayed Location property fisped Catle our of your off states Soil Removal Sundry Ready to be Filed Invasive weads have been removed or sprayed Location property fisped Catles Our of your off states Soil Removal Sundry Ready to be Filed Invasive weads have been removed or sprayed Location property closed Soil Removal Sundry Ready to be Filed Invasive weads have been removed or sprayed Location appendy closed Soil Removal Sundry Ready to be Filed Unvasive weads have been removed or sprayed Location property closed Soil Removal Sundry Ready to be Filed Unvasive weads have been removed or sprayed Location property closed Soil Removal Sundry Ready to be Filed </td <td></td> <td></td> <td></td> <td>1</td> <td></td> <td></td> <td></td>				1			
Has all trash been removed Top soil spread Yards Hauled In: Have all weads been removed Diverations clean and functional Fresh Soil Hauled In: Drainage ditches allow adequate run off Calle guard / gats removed Approval to backful All non-traffic areas disked property Caller / monotable beevered Back fill mechanically compacted All non-traffic areas disked property Caller / monotable beevered Facilities reast All non-traffic areas disked property Caller / monotable Caller / monotable Nodous weeds have been mulched Location properly ripped Calle / monotable Nodous weeds have been removed or sprayed Location represent installed Soil Removal Stundry Ready to be Filed Silt traps are functional Photo transect installed Soil Removal Stundry Ready to be Filed Culverts are functional Barriers in place Soil Removal Stundry Ready to be Filed Upper diversion is functional Barriers in place Soil Removal Stundry Ready to be Filed Photo transect installed Facilities reast Soil Removal Stundry Ready to be Filed Culverts are functional Barriers in place Soil Removal Stundry Ready to be Filed Have weilhead cages and Jersey barriers been removed Pace moved <	- +- + -+			1		┟╼╆═┼═┤	
Have all weeds been removed Diversions clean and functional Approval to backful Training of licks allow valuate access to all facilities Sitt traj clean and functional Approval to backful Draining of licks allow dequate run off Cattle guard / gates removed Back full mechanically compacted All non-traffic areas disked property Cattle guard / gates removed Back full mechanically compacted All non-traffic areas disked property Cattle guard / gates removed Facilities east Nadous weeds have been mulched Ecosion under control Trash and debit removed Invasive weads have been removed or sprayed Location property disked Soil Removal Study to be Filed Sit trap catch have been removed or sprayed Location seeded Soil Removal Study to be Filed Sit trap catch have been removed or sprayed Location seeded Soil Removal Study to be Filed Upper diversion is functional Photo transect installed Facilities catche and for sprayed Upper diversion is functional Photo transect installed & Legible Facilities catche and for sprayed Have wellhead cages and jersey barriers been removed Well sign removed Facilities catche and behave and beh				₩.>		┠╍╌┞╼╼┥	
Teardrop allows vahible access to all facilities Silt trap clean and functional Approval to backfill Drainage ditches allow adequate run off Catile gural / pates removed Back fill mechanically compacted All non-traffic areas disked property Calie or mouse hole covered Facilities area disked property All non-traffic areas disked property Calie or mouse hole covered Facilities area disked in more and debrit removed Seaded areas have been mulched Location property disked Trash and debrit removed Nodous weeds have been removed or sprayed Location property disked Cleae Out Completed Barker set to deter traffic Photo transect installed Sol Removal Study to be Filed Silt traps are functional Photo transect installed Invasive weels have been removed Sol Removal Study to be Filed Cuiverts are functional Photo transect installed Invasive study to the covered Invasive study to the covered Cuiverts are functional Grazing controlled Invasive study to the covered Invasive study to the covered Have wellhead cages and Jersey barriers been removed Well sign removed Invasive study to the debrit removed Invasive study to the debrit removed Growth at least 70% Invasive states Final reclamation photos taken				1:57		╏╾┼╶┿╾╢	
Drainage ditches allow adequate run off Cattle guard / gates removed Back fill mechanically compacted All non-traffic areas disked property Catler / mouse hole covered Facilities resot All non-traffic areas disked property Eroston under control Trash and debit removed Seaded areas have been removed or sprayed Location property disked Cload areas to deter traffic Barriers set to deter traffic Photo transect installed Sol Removal Sundry Ready to be Filed Culversion is functional Photo transect installed Image controlled Upper diversion is functional Grazing controlled Image controlled Photo transect installed Vell sign removed Image controlled Have weilhead cages and jarsey barriers been removed Well sign removed Image controlled Culversion is functional Barriars in place Image controlled Eroston under control Grazing controlled Image controlled Have weilhead cages and jarsey barriers been removed Well sign removed from location Image controlled Renex 70% Image controlled Image controlled Image controlled Bariars in place Image controlled Image controlled Image controlled Ha	-+					┠━╍┼┉╍┼╶─┤	
All non-traffic areas disked property Cellar / mouse hole covered Facilities reset All non-traffic areas seeded Erosion under control Trash and debri removed Seeded areas have been mulched Location properly tipped Cibes Out Completed Noxious weeds have been removed or sprayed Location properly disked Soil Removal Sundry Resety to be Filed Barriers set to deter traffic Photo transect installed Soil Removal Sundry Resety to be Filed Sit traps are functional Public use controlled Image: Soil Controlled Upper diversion is functional Barriars in place Image: Soil Controlled Photo transect installed in under control Grazing controlled Image: Soil Controlled Have wellhead cages and jersey barriers been removed Well sign removed from location Image: Soil Control Contread Contread Control Control Control Control Control Co	-+-+-+			 # 		┡╍┼╍┼╺┥	
All non-traffic areas seeded Eroston under control Trash and debit removed Seaded areas have been mulched Location properly tipped Close Out Completed Noxdous weeds have been removed or sprayed Location properly disked Sol Removal Sundry Ready to be Filed Invasive weeds have been removed or sprayed Location seeded Sol Removal Sundry Ready to be Filed Barters set to deter traffic Photo transect installed Sol Removal Sundry Ready to be Filed Culverts are functional Public use controlled Invasive weeth hatalled Upper diversion is functional Grazing controlled Invasive methods Photo transect installed Invasive weether the stalled Invasive weether the stalled Sit traps are functional Grazing controlled Invasive deter the stalled Upper diversion is functional Grazing controlled Invasive match installed Have wellhead cages and Jersey barriers been removed Well sign removed Invasive match is last 70% Growth at least 70% Trash and debit removed from location Invasive installed Sundry is ready to file Agency inspection Date: Invasive installed				1.7			
Seaded areas have been mulched Location properly tipped Close Out Completed Noxious weeds have been removed or sprayed Location properly disked Soil Removal Sundry Ready to be Filed Invasive weeds have been removed or aprayed Location properly disked Soil Removal Sundry Ready to be Filed Barriers set to deter traffic Photo transect installed Access road properly closed Invasive weeds have been removed or aprayed Silt traps are functional Photo transect installed Access road properly closed Invasive weeds have been removed Upper diversion is functional Barriers in place Invasive seen the functional Invasive use controlled Photo transect installed P&A marker thetalled & Legible Invasive use controlled Invasive seen taken Barriers in place Invasive seen taken Growth at least 70% Invasive seen taken Growth at least 70% Trash and debtirs removed from location Invasive seen taken Sundry is ready to file Agency inspection Date: Invasive seen taken				⊬₽	Emston under control	┟╍┥╼╍┟╍╍┤	
Noxious weeds have been removed or sprayed Location properly disked Invasive weeds have been removed or sprayed Soil Removal Sundry Ready to be Filed Invasive weeds have been removed or sprayed Location seeded Invasive weeds have been removed or sprayed Soil Removal Sundry Ready to be Filed Barliers set to deter traffic Photo transect installed Invasive weeds have been removed or sprayed Invasive weeds have been removed or sprayed Photo transect installed Silt traps are functional Public use controlled Invasive seed in place Invasive weeds have been removed Invasive weeds have been removed Cubrets are functional Barriers in place Invasive seed in place Invasive seed in place Invasive seed in place Erosion under control Grazing controlled Invasive seed seen removed Weil sign removed Have rectamation plotures been removed Weil sign removed Investion Have rectamation plotures been taken Growth at least 70% Investion plotot taken Investion Agency Haperition Date: Final reclamation photos taken Investion Investion				14		╎──┤ ──┤	
Invasive weeds have been removed or sprayed Location seeded Barriers set to deter traffic Photo transect installed Silt traps are functional Access road properly closed Cuiverts are functional Public use controlled Upper diversion is functional Barriers in place Erosion under control Grazing controlled Photo transect installed P&A marker installed & Jegible Have wellhead cages and jersey barriers been removed Well sign removed Have reclamation pictures been taken Growth at least 70% Agency inspection.Date: Final reclamation photos taken Sundry is ready to file Agency inspection.Date:	╾┼╍┼╼┿╍╸					┞─┟╺┽─ ┤	
Barriers sol to deter traffic Photo transect installed Silt traps are functional Access road property closed Culverts are functional Public use controlled Upper diversion is functional Barriers in place Eroston under control Grazing controlled Photo transect installed P&A marker installed & legible Have wellhead cages and jersey barriers been removed Well sign removed Have reclamation pictures been takan Growth at least 70% Growth at least 70% Trash and debris removed from location Sundry is ready to file Agenticy inspection.Daté;	┉╁┈┼╾┼╼	Con Reinoval Ganary Ready to be Field		Ю		╞╌┼╌┤	
Silt traps are functional Access road property closed Image: Culverts are functional Culverts are functional Public use controlled Image: Culverts are functional Upper diversion is functional Barriars in place Image: Culverts are functional Eroston under control Grazing controlled Image: Culverts are functional Photo transect installed P&A marker installed & legible Image: Culverts been removed Have wellhead cages and jersey barriers been removed Well sign removed Image: Culverts basen taken Growth at least 70% Trash and debris removed from location Image: Culverts basen taken Sundry is ready to file Agency inspection.Date: Image: Culverts basen	╾┼╼┿╾┼╼╸	, <u> </u>	-++	ŀА		┼╍┼╌┼╌┤	
Culverts are functional Public use controlled Upper diversion is functional Barriars in place Eroston under control Grazing controlled Photo transect installed P&A marker installed & legible Have wellhead cages and jersey barriers been removed Well sign removed Have reclamation pictures baen taken Growth at least 70% Growth at least 70% Trash and debris removed from location Sundry is ready to file Agency inspection Date;	━╉━╂╾╂╾		-4			┟╍╍┠╺╍┝╾─┤	
Upper diversion is functional Barriars in place Eroston under control Grazing controlled Photo transect installed P&A marker installed & legible Have wellhead cages and jersey barriers been removed Well sign removed Have reclamation plotures been taken Growth at least 70% Growth at least 70% Trash and debris removed from location Agency Inspection Date: Final reclamation photos taken Sundry is ready to file Agency Inspection Date:				4		┝╼┝╼┝━┥	
Eroston under control Grazing controlled Photo transect installed P&A marker installed & legible Have wellhead cages and jersey barriers been removed Well sign removed Have reclamation pictures been taken Growth at least 70% Growth at least 70% Trash and debris removed from location Agenty'Inspecifion.Date: Final reclamation photos taken Sundry is ready to file Agenty'Inspecifion.Date:				44			
Photo transect installed P&A marker installed & Jegible Have wellhead cages and jersey barriers been removed Well sign removed Have reclamation pictures been taken Growth at least 70% Growth at least 70% Trash and debris removed from location Agenty Inspection Date: Final reclamation photos taken Sundry is ready to file Agenty inspection Date;				L1			oper diversion is functional
Have wellhead cages and jersey barriers been removed Well sign removed Have reclamation pictures been taken Growth at least 70% Growth at least 70% Trash and debris removed from location Agency Irispection Date: Final reclamation photos taken Sundry is ready to file Agency inspection Date:			-	11	Grazing controlled		osion under control
Have reclamation pictures been taken Growth at least 70% Growth at least 70% Trash and debris removed from location Agency inspection Date: Final reclamation photos taken Sundry is ready to file Agency inspection Date:				Li A	P&A marker installed & Jegible		noto transect installed
Growth at least 70% Trash and debris removed from location Agency Inspection Date: Final reclamation photos taken Sundry is ready to file Agency Inspection Date:			r = 1	L'X	Well sign removed		ave wellhead cages and jersey barriers been removed
Growth at least 70% Agency Inspection Date: Sundry is ready to file				17	Growth at least 70%		
Agenty Inspection Date: Final reclamation photos taken Sundry is ready to file Agency inspection Date:	-+			+ - 2	Trash and debris removed from location		
Sundry is ready to file					Final reclamation photos taken		ency Inspection Date:
						╏╌╏╌╎	
	╺━┼━┼╾┼╌╸		┝━╄╾┨	1.7	FAN Ready to be filed	┟╌┠╌╴┠╶╍	
Comments: Comments:		Commants	┕──┖╍┥				2000 Antes
Sobmit FAN							