

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company WPX Energy Production	Contact Deborah Watson
Address PO Box 640 Aztec, NM 87410	Telephone No. 505-333-1880
Facility Name Rosa Unit # 041B	Facility Type Well Site

Surface Owner Federal	Mineral Owner Federal (NMSF-078763)	API No. 30-039-27014
-----------------------	-------------------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	06	31N	05W	725	South	1210	East	Rio Arriba

Latitude N36.923431 Longitude W107.399125

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 24 bbl	Volume Recovered 10 bbl
Source of Release Rock basket/transfer pump	Date and Hour of Occurrence unknown	Date and Hour of Discovery 11/22/17 12:10 PM
Was Immediate Notice Given? (within 24-hour notice) <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom? N/A	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.* N/A		



Describe Cause of Problem and Remedial Action Taken.*

Heater went out and rock basket froze and cracked releasing produced water into secondary containment, some fluid seeped under C-ring containment. Transfer pump was shut-in. Water truck called to location to recover standing fluids. Rock basket repaired week of 11/26/2017.

Describe Area Affected and Cleanup Action Taken.*

- A water truck recovered 10 bbl of produced water.
- All fluids remained on location.
- Two composite confirmation samples will be collected from within the area of impact (secondary containment and impacted pad surface). The sample will be laboratory analyzed for TPH (GRO/DRO/MRO), BTEX, and chlorides. Additional cleanup actions will be taken if analytical laboratory results exceed NMOCD action levels based on site ranking.
- WPX will provide notification to BLM-FFO and NMOCD prior to collection of confirmation sample.
- Laboratory analytical results will be included in the Final C-141 report.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Deborah Watson	Approved by Environmental Specialist: 	
Title: Environmental Specialist	Approval Date: 12/8/2017	Expiration Date:
E-mail Address: deborah.watson@wpxenergy.com	Conditions of Approval: Sample Areas as described above	Attached <input type="checkbox"/>
Date: 12/07/2017	Phone: 505-386-9693	

* Attach Additional Sheets If Necessary