

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Hilcorp Energy Company (HEC)	Contact Clara Cardoza
Address 9a CR 5793	Telephone No. 505-564-0733
Facility Name Albright 11	Facility Type Well

Surface Owner Federal	Mineral Owner Federal (SF-077865)	API No. 30-045-25702
-----------------------	-----------------------------------	----------------------

LOCATION OF RELEASE

Unit Letter I	Section 22	Township 29N	Range 10W	Feet from the 1862	North/South Line South	Feet from the 860	East/West Line East	County San Juan
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	----------------------	------------------------	--------------------

Latitude 36.7096252 Longitude -107.8660202 NAD83

NATURE OF RELEASE

Type of Release Historic hydrocarbon	Volume of Release Unknown	Volume Recovered n/a
Source of Release BGT	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 11/28/2017 09:00
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Vanessa Fields NMOCD & Whitney Thomas BLM FFO	
By Whom? Lisa Hunter	Date and Hour 11/28/2017 12:57; 12/28/2017 13:05 left voicemail	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

OIL CONS. DIV DIST. 3

DEC 07 2017



Describe Cause of Problem and Remedial Action Taken.*

Pulled the fiberglass BGT at the Albright 11 for upgrade to the steel pit tank for upcoming frac work and discovered impacted soil beneath tank. Contacted NMOCD to request a 5-point composite sample to be taken.

Describe Area Affected and Cleanup Action Taken.*

Impacted soil removal begin on 11/29. Results from the 5-point composite were unfavorable so HEC continued excavating the visually impacted soil. Thursday Rule Engineering was called to the site to help with the delineation and field testing. Excavation to favorable field results was completed on Thursday 11/30 late afternoon and confirmation sampling was scheduled for Monday 12/4.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION		
Printed Name: Clara Cardoza	Approved by Environmental Specialist 		
Title: Environmental Specialist	Approval Date: <u>12/8/2017</u>	Expiration Date:	
E-mail Address: ccardoza@hilcorp.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 12/05/2017	Phone: 505-564-0733		

* Attach Additional Sheets If Necessary

NVF1734230051