

Submit 1 Copy To Appropriate District Office
District I – (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II – (575) 748-1283
811 S. First St., Artesia, NM 88210
District III – (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV – (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised August 1, 2011

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.) 1. Type of Well: Oil Well <input checked="" type="checkbox"/> Gas Well <input type="checkbox"/> Other <input type="checkbox"/>		WELL API NO. 30-045-35806
2. Name of Operator WPX Energy Production, LLC		5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input type="checkbox"/>
3. Address of Operator P. O. Box 640, Aztec, NM 87410 (505) 333-1808		6. State Oil & Gas Lease No. NO-G-1312-1856
4. Well Location Unit Letter F : 1980' feet from the FNL line and 2471' feet from the FWL line Section 13 Township 23N Range 9W NMPM County San Juan		7. Lease Name or Unit Agreement Name NMNM135216A W Lybrook Unit
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 6700' GR		8. Well Number 751H
		9. OGRID Number 120782
		10. Pool name or Wildcat Lybrook Mancos W

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPL <input type="checkbox"/> DOWNHOLE COMMINGLE <input type="checkbox"/> OTHER: <input type="checkbox"/>	SUBSEQUENT REPORT OF: REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> P AND A <input type="checkbox"/> CASING/CEMENT JOB <input type="checkbox"/> OTHER: INTER-WELL COMMUNICATION <input checked="" type="checkbox"/>
---	--

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

WPX Energy conducted stimulation on the following well:

NMOCD Order: R-14051

Start date: 6/19/17

End date: 6/29/17

Type: Fracture Treatment

Pressure: 6685psi

Volume Average: Nitrogen – 52,361(scf); Sand – 10,945,948(lbs); Fluid – 2,476,483(gals)

Results of any investigation conducted: N/A

OIL CONS. DIV DIST. 3

OCT 06 2017

Attached: Spreadsheet with affected wells due to stimulation activity.

Spud Date:

Rig Release Date:

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Marie E. Florez TITLE Permit Tech DATE 10/5/17

Type or print name Marie E. Florez E-mail address: marie.jaramillo@wpxenergy.com PHONE: (505) 333-1808 For State Use Only

APPROVED BY: Charles TITLE SUPERVISOR DISTRICT #3 DATE DEC 11 2017
Conditions of Approval (if any):

Affected Wells

Well Name	API number	Formation	Operator	Date Affected	Type Communication	Volume of Communication	Highest PSI Observed	Standard Operating PSI	Results of Communication	Results of any Investigation Conducted
W Lybrook Unit 709H	30-045-35741	Lybrook Mancos W	WPX	6/26/2017	Decrease in oil / Increase of water Prod.	N/A	N/A	N/A	Shut In	No Gas Analysis/ well was shut in / No fluids or gas was released during these impacts
W Lybrook Unit 747H	30-045-35742	Lybrook Mancos W	WPX	6/24/2017	Decrease in oil / Loss of water Prod.	N/A	N/A	N/A	Shut In	No Gas Analysis/ well was shut in / No fluids or gas was released during these impacts
Stimulated Well		W Lybrook Unit 751H								